

Test Report


Intertek Report No.: 250522061SZN-005_Appendix C




Band41-15MHz-QPSK-41515-75RB#0




Band41-15MHz-16QAM-39725-75RB#0




Band41-15MHz-16QAM-39765-75RB#0






Band41-15MHz-16QAM-41515-75RB#0




Band41-20MHz-QPSK-39750-100RB#0




Band41-20MHz-QPSK-41490-100RB#0

PS: " Go To Local


Signaling Parameter







Band41-20MHz-16QAM-39790-100RB#0

Go To Local




Band41-20MHz-16QAM-40620-100RB#0







Band66-1.4MHz-QPSK-131979-6RB#0




Band66-1.4MHz-QPSK-132322-6RB#0




Band66-1.4MHz-16QAM-132322-6RB#0












(0<u>7</u>3) Go To Local Intertek Report No.: 250522061SZN-005_Appendix C



Band66-5MHz-16QAM-132322-25RB#0