



CVC Testing Technology (Shenzhen) Co., Ltd.


Test Report No.: FCCSZ2025-0044-RF5-A8

Page 31 of 198

n77(3450-3550)	30	60	DFT-BPSK	M	Outer_Full	12.86	≤13dB	PASS
n77(3450-3550)	30	60	DFT-QPSK	M	Outer_Full	9.77	≤13dB	PASS
n77(3450-3550)	30	60	DFT-BPSK	H	Outer_Full	12.63	≤13dB	PASS
n77(3450-3550)	30	60	DFT-QPSK	H	Outer_Full	10.88	≤13dB	PASS
n77(3450-3550)	30	70	DFT-BPSK	L	Outer_Full	12.08	≤13dB	PASS
n77(3450-3550)	30	70	DFT-QPSK	L	Outer_Full	11.58	≤13dB	PASS
n77(3450-3550)	30	70	DFT-BPSK	M	Outer_Full	10.3	≤13dB	PASS
n77(3450-3550)	30	70	DFT-QPSK	M	Outer_Full	11.73	≤13dB	PASS
n77(3450-3550)	30	70	DFT-BPSK	H	Outer_Full	10.44	≤13dB	PASS
n77(3450-3550)	30	70	DFT-QPSK	H	Outer_Full	11.78	≤13dB	PASS
n77(3450-3550)	30	80	DFT-BPSK	L	Outer_Full	10.81	≤13dB	PASS
n77(3450-3550)	30	80	DFT-QPSK	L	Outer_Full	11.84	≤13dB	PASS
n77(3450-3550)	30	80	DFT-BPSK	M	Outer_Full	10.71	≤13dB	PASS
n77(3450-3550)	30	80	DFT-QPSK	M	Outer_Full	12.45	≤13dB	PASS
n77(3450-3550)	30	80	DFT-BPSK	H	Outer_Full	12.88	≤13dB	PASS
n77(3450-3550)	30	80	DFT-QPSK	H	Outer_Full	8.54	≤13dB	PASS
n77(3450-3550)	30	90	DFT-BPSK	L	Outer_Full	12.32	≤13dB	PASS
n77(3450-3550)	30	90	DFT-QPSK	L	Outer_Full	9.63	≤13dB	PASS
n77(3450-3550)	30	90	DFT-BPSK	M	Outer_Full	8.94	≤13dB	PASS
n77(3450-3550)	30	90	DFT-QPSK	M	Outer_Full	10.04	≤13dB	PASS
n77(3450-3550)	30	90	DFT-BPSK	H	Outer_Full	10.98	≤13dB	PASS
n77(3450-3550)	30	90	DFT-QPSK	H	Outer_Full	11.48	≤13dB	PASS
n77(3450-3550)	30	100	DFT-BPSK	M	Outer_Full	9.78	≤13dB	PASS
n77(3450-3550)	30	100	DFT-QPSK	M	Outer_Full	9.93	≤13dB	PASS




5




NTNV-n77(3450-3550)-PC3-30-15-L-DFT-QPSK-Outer Full-PAS

5



NTNV-n77(3450-3550)-PC3-30-15-M-DFT-QPSK-Outer Full-PAS

5



NTNV-n77(3450-3550)-PC3-30-15-H-DFT-QPSK-Outer Full-PAS

5



CVC Testing Technology (Shenzhen) Co., Ltd.

Test Report No.: FCCS2025-0044-RF5-A8

Page 34 of 198





NTNV-n77(3450-3550)-PC3-30-20-L-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-20-L-DFT-QPSK-Outer_Full-PAS

S

S



NTNV-n77(3450-3550)-PC3-30-20-M-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-20-M-DFT-QPSK-Outer_Full-PAS

S

S



NTNV-n77(3450-3550)-PC3-30-20-H-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-20-H-DFT-QPSK-Outer_Full-PAS

S



S



CVC Testing Technology (Shenzhen) Co., Ltd.

Test Report No.: FCCS2025-0044-RF5-A8

Page 35 of 198





NTNV-n77(3450-3550)-PC3-30-30-L-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-30-L-DFT-QPSK-Outer_Full-PAS

S

S



NTNV-n77(3450-3550)-PC3-30-30-M-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-30-M-DFT-QPSK-Outer_Full-PAS

S

S




NTNV-n77(3450-3550)-PC3-30-30-H-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-30-H-DFT-QPSK-Outer_Full-PAS

S

S




NTNV-n77(3450-3550)-PC3-30-40-L-DFT-QPSK-Outer Full-PAS

5



NTNV-n77(3450-3550)-PC3-30-40-M-DFT-QPSK-Outer Full-PAS

5



NTNV-n77(3450-3550)-PC3-30-40-H-DFT-QPSK-Outer Full-PAS


5



CVC Testing Technology (Shenzhen) Co., Ltd.

Test Report No.: FCCS2025-0044-RF5-A8

Page 37 of 198



NTNV-n77(3450-3550)-PC3-30-50-L-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-50-L-DFT-QPSK-Outer_Full-PAS

S

S



NTNV-n77(3450-3550)-PC3-30-50-M-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-50-M-DFT-QPSK-Outer_Full-PAS

S

S



NTNV-n77(3450-3550)-PC3-30-50-H-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-50-H-DFT-QPSK-Outer_Full-PAS

S


S



CVC Testing Technology (Shenzhen) Co., Ltd.

Test Report No.: FCCS2025-0044-RF5-A8

Page 38 of 198





NTNV-n77(3450-3550)-PC3-30-60-L-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-60-L-DFT-QPSK-Outer_Full-PAS

S

S




NTNV-n77(3450-3550)-PC3-30-60-M-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-60-M-DFT-QPSK-Outer_Full-PAS

S

S



NTNV-n77(3450-3550)-PC3-30-60-H-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-60-H-DFT-QPSK-Outer_Full-PAS

S


S



CVC Testing Technology (Shenzhen) Co., Ltd.

Test Report No.: FCCS2025-0044-RF5-A8

Page 39 of 198





NTNV-n77(3450-3550)-PC3-30-70-L-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-70-L-DFT-QPSK-Outer_Full-PAS

S

S



NTNV-n77(3450-3550)-PC3-30-70-M-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-70-M-DFT-QPSK-Outer_Full-PAS

S

S



NTNV-n77(3450-3550)-PC3-30-70-H-DFT-BPSK-Outer_Full-PAS

NTNV-n77(3450-3550)-PC3-30-70-H-DFT-QPSK-Outer_Full-PAS


S

S




NTNV-n77(3450-3550)-PC3-30-80-L-DFT-QPSK-Outer Full-PAS

5



NTNV-n77(3450-3550)-PC3-30-80-M-DFT-QPSK-Outer Full-PAS

0



NTNV-n77(3450-3550)-PC3-30-80-H-DFT-QPSK-Outer Full-PAS

5