



15MHz_Middle_16QAM_75@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:35:53




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:36:03


15MHz_High_QPSK_75@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:36:28




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:36:37


15MHz_High_16QAM_75@0

Occupied Bandwidth

26dB Bandwidth




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:36:59



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:37:07


20MHz_Low_QPSK_100@0

Occupied Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:38:03


26dB Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:38:10


20MHz_Low_16QAM_100@0

Occupied Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:53:57


26dB Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:54:05


20MHz_Middle_QPSK_100@0

Occupied Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:54:29

26dB Bandwidth




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 16:54:38


20MHz_Middle_16QAM_100@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny LI
Date: 13.JUN.2025 16:55:03




ProjectNo.:2504S07338E-RF Tester:Benny LI
Date: 13.JUN.2025 16:55:12


20MHz_High_QPSK_100@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny LI
Date: 13.JUN.2025 16:55:35




ProjectNo.:2504S07338E-RF Tester:Benny LI
Date: 13.JUN.2025 16:55:44


20MHz_High_16QAM_100@0

Occupied Bandwidth

26dB Bandwidth



ProjectNo.:2504S07338E-RF Tester:Benny LI
Date: 13.JUN.2025 16:56:07




ProjectNo.:2504S07338E-RF Tester:Benny LI
Date: 13.JUN.2025 16:56:15

Spurious Emissions at Antenna Terminal

FCC Part 22H


LTE Band 5, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504807338E-RF Tester:Benny LI
Date: 17.JUN.2025 09:33:54

1.4MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504807338E-RF Tester:Benny LI
Date: 17.JUN.2025 09:34:01

1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504807338E-RF Tester:Benny LI
Date: 17.JUN.2025 09:34:09

1.4MHz_Low_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2504807338E-RF Tester:Benny LI
Date: 17.JUN.2025 09:34:15

1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504807338E-RF Tester:Benny LI
Date: 17.JUN.2025 09:34:22

1.4MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504807338E-RF Tester:Benny LI
Date: 17.JUN.2025 09:34:29

1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:34:36

1.4MHz_Middle_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:34:43

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:34:50

1.4MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:34:56

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:35:04

1.4MHz_High_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:35:10

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:35:49

3MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:35:55

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:36:03

3MHz_Low_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:36:10

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:36:18

3MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:36:24

3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:36:32

3MHz_Middle_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:36:39

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:36:46

3MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:36:53

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:37:00

3MHz_High_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:37:07

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:38:40

5MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:38:48

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:38:56

5MHz_Low_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:39:03

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:39:11

5MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:39:17

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:39:25

5MHz_Middle_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:39:32

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:39:40

5MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:39:47

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:39:55

5MHz_High_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:40:02

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:40:42

10MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:40:49

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:40:58

10MHz_Low_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:41:05

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:41:13

10MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:41:21

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:41:29

10MHz_Middle_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:41:37

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:41:46

10MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:41:53

10MHz_High_QPSK_50@0(30MHz~1GHz)



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:42:02

10MHz_High_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 17.JUN.2025 09:42:09


FCC Part 24E

LTE Band 2, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




1.4MHz_Low_QPSK_1@0(1GHz~20.1GHz)




1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




1.4MHz_Low_QPSK_6@0(1GHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)



1.4MHz_Middle_QPSK_1@0(1GHz~20.1GHz)




1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:35:12

1.4MHz_Middle_QPSK_6@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:35:31

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:35:50

1.4MHz_High_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:36:10

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:36:29

1.4MHz_High_QPSK_6@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:36:49

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:38:17

3MHz_Low_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:38:37

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:38:55

3MHz_Low_QPSK_15@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:39:15

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:39:33

3MHz_Middle_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:39:53

3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:40:12

3MHz_Middle_QPSK_15@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:40:31

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:40:50

3MHz_High_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:41:10

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:41:29

3MHz_High_QPSK_15@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:41:48

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:43:15

5MHz_Low_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:43:35

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:43:54

5MHz_Low_QPSK_25@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:44:13

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:44:32

5MHz_Middle_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:44:51

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:45:09

5MHz_Middle_QPSK_25@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:45:29

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:45:47

5MHz_High_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:46:07

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:46:26

5MHz_High_QPSK_25@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:46:47

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:48:36

10MHz_Low_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:49:02

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:49:53

10MHz_Low_QPSK_50@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:50:49

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:51:50

10MHz_Middle_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:52:44

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:53:37

10MHz_Middle_QPSK_50@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:54:08

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:54:27

10MHz_High_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:54:46

10MHz_High_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:55:05

10MHz_High_QPSK_50@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:55:25

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:56:53

15MHz_Low_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:57:13

15MHz_Low_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:57:31

15MHz_Low_QPSK_75@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:57:51

15MHz_Middle_QPSK_1@0(30MHz~1GHz)



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:58:10

15MHz_Middle_QPSK_1@0(1GHz~20.1GHz)



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 16:59:08