




15MHz_Middle_QPSK_75@0(30MHz~1GHz)




15MHz_Middle_QPSK_75@0(1GHz~20.1GHz)




15MHz_High_QPSK_1@0(30MHz~1GHz)




15MHz_High_QPSK_1@0(1GHz~20.1GHz)




15MHz_High_QPSK_75@0(30MHz~1GHz)



15MHz_High_QPSK_75@0(1GHz~20.1GHz)




20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:02:46

20MHz_Low_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:03:06

20MHz_Low_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:03:26

20MHz_Low_QPSK_100@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:03:46

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:04:05

20MHz_Middle_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:04:26

20MHz_Middle_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:04:45

20MHz_Middle_QPSK_100@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:05:05

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:05:24

20MHz_High_QPSK_1@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:05:45

20MHz_High_QPSK_100@0(30MHz~1GHz)



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:06:04

20MHz_High_QPSK_100@0(1GHz~20.1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 17:06:24


FCC Part 27

LTE Band 4, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




1.4MHz_Low_QPSK_1@0(1GHz~18.55GHz)




1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




1.4MHz_Low_QPSK_6@0(1GHz~18.55GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)



1.4MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:13:40

1.4MHz_Middle_QPSK_6@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:14:01

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:14:21

1.4MHz_High_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:14:44

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:15:05

1.4MHz_High_QPSK_6@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:15:26

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:16:29

3MHz_Low_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:16:51

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:17:11

3MHz_Low_QPSK_15@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:17:33

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:17:53

3MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:18:14

3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:18:35

3MHz_Middle_QPSK_15@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:18:56

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:19:17

3MHz_High_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:19:38

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:19:59

3MHz_High_QPSK_15@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:20:20

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:21:25

5MHz_Low_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:21:46

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:22:07

5MHz_Low_QPSK_25@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:22:29

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:22:50

5MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:23:11

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:23:32

5MHz_Middle_QPSK_25@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:23:54

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:24:15

5MHz_High_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:24:38

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:24:59

5MHz_High_QPSK_25@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:25:21

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:27:37

10MHz_Low_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:27:59

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:28:20

10MHz_Low_QPSK_50@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:28:42

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:29:03

10MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:29:25

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:29:47

10MHz_Middle_QPSK_50@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:30:08

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:30:29

10MHz_High_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:30:51

10MHz_High_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:31:12

10MHz_High_QPSK_50@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:31:34

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:32:28

15MHz_Low_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:32:50

15MHz_Low_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:33:12

15MHz_Low_QPSK_75@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:33:33

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:33:55

15MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:34:17

15MHz_Middle_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:34:39

15MHz_Middle_QPSK_75@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:35:00

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:35:22

15MHz_High_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:35:44

15MHz_High_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:36:06

15MHz_High_QPSK_75@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:36:28

20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:37:23

20MHz_Low_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:37:45

20MHz_Low_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:38:07

20MHz_Low_QPSK_100@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:38:29

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:38:50

20MHz_Middle_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:39:12

20MHz_Middle_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:39:34

20MHz_Middle_QPSK_100@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:39:56

20MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:40:18

20MHz_High_QPSK_1@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:40:40

20MHz_High_QPSK_100@0(30MHz~1GHz)



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:41:02

20MHz_High_QPSK_100@0(1GHz~18.55GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 12.JUN.2025 18:41:24

LTE Band 7, Normal


1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:07:08

5MHz_Low_QPSK_1@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:07:20

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:07:27

5MHz_Low_QPSK_25@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:07:38

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:07:45

5MHz_Middle_QPSK_1@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:07:57

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:08:04

5MHz_Middle_QPSK_25@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:08:15

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:08:22

5MHz_High_QPSK_1@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:08:34

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:08:42

5MHz_High_QPSK_25@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:08:54

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:10:09

10MHz_Low_QPSK_1@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:10:20

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:10:27

10MHz_Low_QPSK_50@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:10:39

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:10:46

10MHz_Middle_QPSK_1@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:10:58

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:11:05

10MHz_Middle_QPSK_50@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:11:17

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:11:25

10MHz_High_QPSK_1@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:11:36

10MHz_High_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:11:44

10MHz_High_QPSK_50@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:11:56

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:13:11

15MHz_Low_QPSK_1@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:13:23

15MHz_Low_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:13:31

15MHz_Low_QPSK_75@0(1GHz~26.7GHz)




ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:13:43

15MHz_Middle_QPSK_1@0(30MHz~1GHz)



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:13:50

15MHz_Middle_QPSK_1@0(1GHz~26.7GHz)



ProjectNo.:2504S07338E-RF Tester:Benny Li
Date: 13.JUN.2025 10:14:02