






































NTNV_N78-3450-3550_PC2_30_90_M_TID6_N/A
_0.009_0.15_#1NTNV_N78-3450-3550_PC2_30_90_M_TID6_N/A
_0.15_30_#1NTNV_N78-3450-3550_PC2_30_90_M_TID6_N/A
_30_1000_#1NTNV_N78-3450-3550_PC2_30_90_M_TID6_N/A
_1000_3000_#1NTNV_N78-3450-3550_PC2_30_90_M_TID6_N/A
_3000_12000_#1NTNV_N78-3450-3550_PC2_30_90_M_TID6_N/A
_12000_20000_#1

