

Certification Exhibit

Test Photos

Innara Health Inc.
NTRAINER SYSTEM 2.0

FCC ID: 2A9ATIN-5001

Prepared for: Innara Health Inc.
10900 S Clay Blair Blvd
Olathe, Kansas 66061 USA



America

**Add value.
Inspire trust.**

COMMERCIAL-IN-CONFIDENCE

Document Number: NC72183115.4 | Issue: 1

SIGNATURE

A handwritten signature in black ink, appearing to read "Sean Sellergren".

NAME	JOB TITLE	RESPONSIBLE FOR	ISSUE DATE
Sean Sellergren	Sr. EMC Engineer	Authorized Signatory	08 November 2022

Signatures in this approval box have checked this document in line with the requirements of TÜV SÜD America, Inc. document control rules.

FCC Accreditation Designation Number US1148 New Brighton, MN Test Laboratory	Innovation, Science, and Economic Development Canada Accreditation Site Number 4512A New Brighton, MN Test Laboratory
--	---



Contents

1.1 EUT Photo3

1.2 Conducted Emissions.....4

1.3 Radiated Emissions.....5

1.4 Restricted Band-edge photos..... **Error! Bookmark not defined.**

1.1 EUT Photo



Photo 1.1-1 – EUT Front View

Photo is of the transmitter outside of the plastic enclosure.

1.2 Conducted Emissions



Photo 1.2-1 – Conducted Test Setup

1.3 Radiated Emissions





Photo 1.3-1 – RE Spurious Emissions 30-1000 MHz



TÜV SÜD America Inc
141 14th Street NW
New Brighton, MN 55112

Phone: 651-631-2487
www.tuv-sud-america.com



Photo 1.3-2 – RE Spurious Emissions 1-18 GHz

TÜV SÜD America Inc
141 14th Street NW
New Brighton, MN 55112

Phone: 651-631-2487
www.tuv-sud-america.com