






11AC80SISO_Ant1_5610





11AC80SISO_Ant1_5690






99% Bandwidth






Date: 3.FEB.2023 17:09:13

11A Ant0 5280




Date: 3.FEB.2023 17:12:08

11A Ant0 5320




Date: 3.FEB.2023 17:14:07


11A Ant0 5500




11A Ant0 5580



11A Ant0 5700




11A Ant0 5720




Date: 3 FEB 2023 17:24:21

11A Ant0 5745




Date: 3 FEB 2023 17:27:08

11A Ant0 5785




Date: 3 FEB 2023 17:29:21


11A Ant0 5825




11N20SISO_Ant0_5180




11N20SISO_Ant0_5200




11N20SISO_Ant0_5240




11N20SISO_Ant0_5260




11N20SISO_Ant0_5280




11N20SISO_Ant0_5320




11N20SISO_Ant0_5500



11N20SISO_Ant0_5580




11N20SISO_Ant0_5700




Date: 3 FEB 2023 17:52:49

11N20SISO_Ant0_5720




Date: 4 FEB 2023 09:31:41

11N20SISO_Ant0_5745




Date: 4 FEB 2023 09:34:30

11N20SISO_Ant0_5785



Date: 4 FEB 2023 09:36:48

11N20SISO_Ant0_5825




Date: 4 FEB 2023 09:38:47

11N40SISO_Ant0_5190




Date: 4 FEB 2023 09:41:00

11N40SISO_Ant0_5230




Date: 4 FEB 2023 09:43:06

11N40SISO_Ant0_5270



Date: 4 FEB 2023 09:44:46

11N40SISO_Ant0_5310



Date: 4 FEB 2023 09:46:28

11N40SISO_Ant0_5510



Spectrum

Ref Level 20.00 dBm Offset 1.00 dB RBW 1 MHz
 Att 30 dB SWT 1 ms VBW 3 MHz Mode Auto Sweep
 Count 500/500

1Pk View

10 dBm
 0 dBm
 -10 dBm
 -20 dBm
 -30 dBm
 -40 dBm
 -50 dBm
 -60 dBm
 -70 dBm

M1[1]
 Occ BW
 T1
 T2

7.60 dBm
 5.5480300 GHz
 36.363636364 MHz

CF 5.55 GHz 1001 pts Span 80.0 MHz

Date: 4 FEB 2023 09:50:20

Spectrum

Ref Level 20.00 dBm Offset 1.00 dB RBW 1 MHz
 Att 30 dB SWT 1 ms VBW 3 MHz Mode Auto Sweep
 Count 500/500

1Pk View

10 dBm
 0 dBm
 -10 dBm
 -20 dBm
 -30 dBm
 -40 dBm
 -50 dBm
 -60 dBm
 -70 dBm

M1[1]
 7.71 dBm
 5.672720 GHz
 36.363636364 mW

CF 5.67 GHz 1001 pts Span 80.0 MHz


Date: 4 FEB 2023 09:52:02

Page 62 of 426




Date: 4 FEB 2023 09:59:26

11N40SISO Ant0 5755




Date: 4 FEB 2023 09:56:45

11N40SISO Ant0 5795




Date: 4 FEB 2023 10:02:27


11AC20SISO Ant0 5180




11AC20SISO_Ant0_5200



11AC20SISO_Ant0_5240




11AC20SISO_Ant0_5260




Date: 4 FEB 2023 10:11:10

11AC20SISO_Ant0_5280




Date: 4 FEB 2023 10:12:47

11AC20SISO_Ant0_5320




Date: 4 FEB 2023 10:14:26


11AC20SISO_Ant0_5500




11AC20SISO_Ant0_5580



11AC20SISO_Ant0_5700




11AC20SISO_Ant0_5720




Date: 4 FEB 2023 10:21:54

11AC20SISO_Ant0_5745




Date: 4 FEB 2023 10:24:39

11AC20SISO_Ant0_5785




Date: 4 FEB 2023 10:27:03

11AC20SISO_Ant0_5825




Date: 4 FEB 2023 10:29:12

11AC40SISO_Ant0_5190



Date: 4 FEB 2023 10:31:40

11AC40SISO_Ant0_5230




Date: 4 FEB 2023 10:33:30

11AC40SISO_Ant0_5270




Date: 4 FEB 2023 10:35:16

11AC40SISO_Ant0_5310



Date: 4 FEB 2023 10:36:53

11AC40SISO_Ant0_5510



Date: 4 FEB 2023 10:38:45

11AC40SISO_Ant0_5550




Date: 4 FEB 2023 10:40:36

11AC40SISO_Ant0_5670




Date: 4 FEB 2023 10:42:18

11AC40SISO_Ant0_5710




Date: 4 FEB 2023 10:44:14

11AC40SISO_Ant0_5755




Date: 4 FEB 2023 10:46:58

11AC40SISO Ant0 5795




Date: 4 FEB 2023 10:49:13

11AC80SISO Ant0 5210




Date: 4 FEB 2023 10:51:19

11AC80SISO Ant0 5290




Date: 4 FEB 2023 10:53:10

11AC80SISO Ant0 5530




Date: 4 FEB 2023 10:55:05

11AC80SISO Ant0 5610




Date: 4 FEB 2023 10:56:59

11AC80SISO Ant0 5690




Date: 4 FEB 2023 10:59:01

11AC80SISO Ant0 5775




Date: 4 FEB 2023 11:01:42

11A Ant1 5180




Date: 4 FEB 2023 11:52:48


11A Ant1 5200




11A Ant1 5240




11A Ant1 5260




11A Ant1 5280




11A Ant1 5320



11A Ant1 5500




11A Ant1 5580




Date: 4 FEB 2023 12:06:50

11A Ant1 5700




Date: 4 FEB 2023 12:08:34

11A Ant1 5720




Date: 4 FEB 2023 12:10:26


11A Ant1 5745




11A Ant1 5785



11A Ant1 5825




11N20SISO Ant1 5180




Date: 4 FEB 2023 12:55:24

11N20SISO_Ant1_5200




Date: 4 FEB 2023 12:57:15

11N20SISO_Ant1_5240




Date: 4 FEB 2023 12:58:55

11N20SISO_Ant1_5260




Date: 4 FEB 2023 13:01:54

11N20SISO_Ant1_5280




Date: 4 FEB 2023 13:04:59

11N20SISO_Ant1_5320




Date: 4 FEB 2023 13:15:48


11N20SISO_Ant1_5500




11N20SISO_Ant1_5580



11N20SISO_Ant1_5700




11N20SISO_Ant1_5720




Date: 4 FEB 2023 13 25 01

11N20SISO_Ant1_5745




Date: 4 FEB 2023 13 27 23

11N20SISO_Ant1_5785




Date: 4 FEB 2023 13 36 49

11N20SISO_Ant1_5825




Date: 4 FEB 2023 13:38:43

11N40SISO Ant1 5190




Date: 4 FEB 2023 13:40:44

11N40SISO Ant1 5230



Date: 4 FEB 2023 13:42:38

11N40SISO Ant1 5270




Date: 4 FEB 2023 13:44:30

11N40SISO_Ant1_5310




Date: 4 FEB 2023 13:46:11

11N40SISO_Ant1_5510




Date: 4 FEB 2023 13:48:02


11N40SISO_Ant1_5550




11N40SISO_Ant1_5670




11N40SISO_Ant1_5710




11N40SISO_Ant1_5755




11N40SISO Ant1 5795



11AC20SISO Ant1 5180




11AC20SISO Ant1 5200




Date: 4 FEB 2023 14:03:20

11AC20SISO_Ant1_5240




Date: 4 FEB 2023 14:05:02

11AC20SISO_Ant1_5260




Date: 4 FEB 2023 14:06:36

11AC20SISO_Ant1_5280




Date: 4 FEB 2023 14:08:13

11AC20SISO_Ant1_5320




Date: 4 FEB 2023 14:09:49

11AC20SISO_Ant1_5500




Date: 4 FEB 2023 14:11:39

11AC20SISO_Ant1_5580




Date: 4 FEB 2023 14:13:34

11AC20SISO_Ant1_5700




Date: 4 FEB 2023 14:15:14

11AC20SISO_Ant1_5720




Date: 4 FEB 2023 14:17:05

11AC20SISO_Ant1_5745




Date: 4 FEB 2023 14:19:49

11AC20SISO_Ant1_5785



Date: 4 FEB 2023 14:22:20

11AC20SISO_Ant1_5825




Date: 4 FEB 2023 14:24:15

11AC40SISO_Ant1_5190




Date: 4 FEB 2023 14:26:30

11AC40SISO_Ant1_5230




Date: 4 FEB 2023 14:28:24

11AC40SISO_Ant1_5270




Date: 4 FEB 2023 14:30:02

11AC40SISO_Ant1_5310




Date: 4 FEB 2023 14:31:38

11AC40SISO_Ant1_5510




Date: 4 FEB 2023 14:33:38

11AC40SISO_Ant1_5550




Date: 4 FEB 2023 14:35:29

11AC40SISO_Ant1_5670




Date: 4 FEB 2023 14:37:24

11AC40SISO_Ant1_5710




Date: 4 FEB 2023 14:39:57

11AC40SISO_Ant1_5755




Date: 4 FEB 2023 14:42:41

11AC40SISO_Ant1_5795




Date: 4 FEB 2023 14:45:12

11AC80SISO_Ant1_5210




Date: 4 FEB 2023 14:47:50

11AC80SISO_Ant1_5290




Date: 4 FEB 2023 14:49:45

11AC80SISO_Ant1_5530




Date: 4 FEB 2023 14:52:29

11AC80SISO_Ant1_5610



Date: 4 FEB 2023 14:54:21

11AC80SISO_Ant1_5690



Date: 4 FEB 2023 14:56:15

11AC80SISO_Ant1_5775




11A_Ant0_5745




11A_Ant0_5785




Page 95 of 426




11N20SISO_Ant0_5745




11N20SISO_Ant0_5785




11N20SISO_Ant0_5825




11N40SISO Ant0 5755




11N40SISO Ant0 5795




11AC20SISO Ant0 5745




11AC20SISO_Ant0_5785




11AC20SISO_Ant0_5825




11AC40SISO_Ant0_5755




11AC40SISO Ant0 5795




11AC80SISO Ant0 5775




11A Ant1 5745



11A_Ant1_5785



11A_Ant1_5825



11N20SISO_Ant1_5745