

April 24, 2014

## Federal Communications Commission

Office of Engineering and Technology  
Laboratory Division

Inquiry to modify Grant of Equipment Authorization  
FCC ID: 2AA8Z-XRPAD4336  
Date of Grant: 12/23/2013

To whom it may concern,

This letter is in regards to TCB certification of the PerkinElmer Medical Imaging, Digital X-Ray Detector System, operating in the 5.15 – 5.25 GHz UNII band.

The frequency range on the Grant has been mistakenly written as 5.18 – 5.32 GHz. The correct frequency range is 5.18 – 5.24 GHz.

TCB is requesting that the application be put into audit mode to make the necessary correction.

This Inquiry is made according to the KDB 546630.

The Tracking Number: 562507

Thank you.

TCB Reviewer



An Independent Organization Testing for Safety and Performance

Page 1 of 1



This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the Intertek name or one of its marks for sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report by itself does not imply that the material, product or service is or has ever been under an Intertek certification program.



**Intertek Testing Services NA, Inc.**

1365 Adams Ct., Menlo Park CA 94025

Telephone: 1-650-463-2900 Fax: 1-650-463-2910 Web: [www.intertek-etlsemko.com](http://www.intertek-etlsemko.com)

SD 12.1.2 (2/21/07) Informative