

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RSEN421
23-0081
June 19, 2023
SwipeSense, Inc.
Sidecar

EXTERNAL PHOTOGRAPHS



Figure 1. Top of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RSEN421
23-0081
June 19, 2023
SwipeSense, Inc.
Sidecar




Figure 2. Back of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RSEN421
23-0081
June 19, 2023
SwipeSense, Inc.
Sidecar



Figure 3. Left Side of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RSEN421
23-0081
June 19, 2023
SwipeSense, Inc.
Sidecar



Figure 4. Right Side of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RSEN421
23-0081
June 19, 2023
SwipeSense, Inc.
Sidecar



Figure 5. Front of EUT

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RSEN421
23-0081
June 19, 2023
SwipeSense, Inc.
Sidecar




Figure 6. Bottom of EUT