

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
2ABLX-QM150402FM
8832A-QM150402FM
15-0240
October 1, 2015
Qmotion Incorporated
QM150402FM

EXTERNAL PHOTOGRAPHS



Figure 1. Top of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
2ABLX-QM150402FM
8832A-QM150402FM
15-0240
October 1, 2015
Qmotion Incorporated
QM150402FM



Figure 2. Bottom of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
2ABLX-QM150402FM
8832A-QM150402FM
15-0240
October 1, 2015
Qmotion Incorporated
QM150402FM



Figure 3. Left Side of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
2ABLX-QM150402FM
8832A-QM150402FM
15-0240
October 1, 2015
Qmotion Incorporated
QM150402FM



Figure 4. Right Side of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
2AB LX-QM150402FM
8832A-QM150402FM
15-0240
October 1, 2015
Qmotion Incorporated
QM150402FM



Figure 5. Front of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
2ABLX-QM150402FM
8832A-QM150402FM
15-0240
October 1, 2015
Qmotion Incorporated
QM150402FM




Figure 6. Back of EUT