

Shenzhen Fortuneship Technology Co., LTD

Address: Room 501,the 5th Floor,Block B,Digital Building,Garden City,No.1079 Nanhai Road,  
Nanshan District, Shenzhen,Guangdong,China

Attestation Letter

June 11, 2015

To:  
Bay Area Compliance Laboratories Corp.  
1274 Anvilwood Avenue  
Sunnyvale, CA 94089

Dear Sir or Madam:

The RF chip, model: PMB9102, installed in our product Smart Phone, model:  
SP5026i (FCC ID: 2ABXISP5026I) which supports EDGE functions. For using in the  
USA, this chip will only support downlink, not support/enable the uplink.


Best Regards,

Sincerely,

Signature

Huang Fang

Human Resource Director

A handwritten signature in black ink, appearing to read 'Huang Fang', written over the printed name and title.