

Date: July 27th, 2015

Attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern:

The Image Recognition Integrated Systems S.A. (I.R.I.S.S.A), IRISPen 7 Air, Model 2.0, FCC ID: 2ACJL-PENAIR7, and label are so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3)

“This device complies with Part 15 of the FCC Rules.


Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation.”

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Sincerely,


Yves Halleux
Logistics, Purchasing and Back Office Director

I.R.I.S. S.A.



16 Oppenheimer St.
Park Tamar, Rehovot,
Israel, 76701

Tel: 972-8-936-3136
Fax: 972-8-936-5977
www.aeroscout.com

Image Recognition Integrated Systems s.a./n.v.

Rue du Bosquet 10
Parc Scientifique de Louvain-la-Neuve
B-1435 Mont-Saint-Guibert
Belgium

Tel: +32-(0)10-45 13 64
Fax: +32-(0)10-45 34 43
info@iriscorporate.com
www.iriscorporate.com

VAT BE 0430.824.708 - RPM Nivelles
CBC Bank 192-6099602-90
BNP Paribas Fortis 271-0315980-83
Befius Banque 564-5136016-50

IBAN BE34 1926 0996 0290
IBAN BE14 2710 3159 8083
IBAN BE86 5645 1360 1650

BIC CREGBEBB
BIC GEBABEBB
BIC GKCCBEBB