	Report No: <b>R3370</b> Issue No: <b>1</b>	<b>FCC ID: 2ACKT-OTOTO1</b>	
	Test No: <b>T5219</b>	<b>Test Photos</b>	Page: <b>1 of 3</b>



**dB Technology**

( Cambridge Ltd. )

EMC  
Testing

EMC  
Consultancy

EMC  
Training

23, Headington Drive,  
Cambridge.  
CB1 9HE  
Tel : 01954 251974 (test site)  
or : 01223 241140 (accounts)  
Fax : 01954 251907  
web : www.dbtechnology.co.uk  
email: mail@dbtechnology.co.uk

## PHOTOS FILE for FCC EMC TESTS

Performed at:  
**TWENTY PENCE TEST SITE**

**Twenty Pence Road,  
Cottenham,  
Cambridge  
U.K.  
CB24 8PS**

on

**Dentaku London**

**Ototo**

dated


**17th July 2014**

### Document History


Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	23/07/14		Initial release		

Based on report template:  
v090319

*This report shall not be reproduced except in full, without the written approval of:  
dB Technology (Cambridge) Ltd.*

	Report No: <b>R3370</b>	<b>FCC ID: 2ACKT-OTOTO1</b>	
	Issue No: <b>1</b>		
	Test No: <b>T5219</b>	<b>Test Photos</b>	Page: 2 of 3


**Photograph 1 Radiated Emissions: Front view**




**Photograph 2 Radiated Emissions: Front view**





	Report No: <b>R3370</b>	<b>FCC ID: 2ACKT-OTOTO1</b>	
	Issue No: <b>1</b>		
	Test No: <b>T5219</b>	<b>Test Photos</b>	Page: <b>3 of 3</b>

**Photograph 3 Conducted Emissions setup**



**Photograph 4 Conducted Emissions: LISN connection**

