



November 18, 2014

Federal Communications Commission
445 12th Street SW
Washington, DC 20554

Regarding: Cokiya FCC ID: 2ADNA-S10

Subject: Request to change in identification per section 2.933 of FCC rules

This application for Change of Identification requests a new FCC ID as stipulated in 47CFR 2.933(b) for presently authorized equipment.

New FCC ID: 2ADNA-S10 for Cokiya's: 'Broadcom Module BCM20732S'.

The original grant to Broadcom Corporation for Broadcom Module BCM20732S with FCC ID: QDS-BRCM1078 remains in effect.

An authorization letter by Broadcom Corporation is

attached. Per 2.933(b)

1. The original identification is FCC ID: QDS-BRCM1078.
2. The original grant date is 11/06/2013.
3. The equipment is electrically identical. Only the model name model name, trade name, and FCC ID are different.
4. The original test results are applicable and representative of this changed device.
5. Label identification is included in this application.

Sincerely,

A handwritten signature in black ink, appearing to read 'Steve Yarnall'.

Steve Yarnall
COO, Principal
Cokiya Inc.