

AcSiP Technology Corp.
9F, No. 242, Bo'ai St., Shulin Dist., New Taipei City 238005, Taiwan
(R.O.C.)

Professional Installation Attestation

27 August 2021

FCC ID: 2ADWC-AI50H

To Whom It May Concern:

Please be advised that due to the unique Market and function targeted by this product, this product will need special trained professional in configuring and installing the product. We hereby declare that the product will be distributed through controlled distribution channel which has special trained professional to install this product and will not be sold directly to the general public through retail store.

Thank you for your attention.

Yours sincerely,

Jim Wang 2021.8.7
Name: Jim Wang / Title: Engineer
Tel: +886-2-8685-9877 # 249
Fax: +886-2-8685-9577
E-mail: jim@acsip.com.tw