



Please refer to following plots:


Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)



Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:12:03

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:12:28

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:13:04

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:13:32

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:14:06

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:14:34

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:15:07

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:15:29

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:16:05

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:16:27

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:16:58

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:17:23

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:17:59

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:18:21

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:18:51

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:19:16

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:19:53

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:20:16

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:20:43

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:21:02

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:21:36

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:21:58

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:22:38

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:23:01

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:23:30

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:23:59

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:24:31

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:25:00

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:25:34

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:25:59

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:26:36

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:27:01

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:27:34

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:27:56

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:28:27

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:28:46

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:29:12

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:29:38

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:30:07

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:30:30

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:31:00

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:31:25

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:31:48

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:32:14

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:32:46

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:33:15

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:33:48

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:34:14

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:34:49

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:35:12

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:35:44

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:36:07

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:36:41

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:37:04

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:37:37

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:37:57

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:38:30

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:38:56

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:39:33

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:39:58

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:40:31

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:40:57

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:41:29

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:41:49

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:42:22

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:42:54

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:43:24

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:43:53

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:44:28

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.DEC.2021 08:44:51

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:45:21

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:45:47

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:46:07

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:46:29

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:46:58

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:47:24

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:47:45

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:48:04

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:48:36

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:49:02

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:49:34

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:49:57

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:50:27

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:50:53

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:51:22

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:51:44

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:52:11

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:52:36


Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)



Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:54:10

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 14.DEC.2021 08:54:35


Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)



Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:56:05

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 08:56:27

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:57:00

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 08:57:28

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:57:54

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 08:58:17

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:58:48

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 08:59:11

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 08:59:41

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:00:07

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:00:34

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:00:59

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:01:36

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:01:58

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:02:28

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:02:50

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:03:26

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:03:49

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:04:19

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:04:38

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:05:08

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:05:27

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:06:00

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:06:22

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:42:17

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:42:40

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:43:09

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:43:35

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:44:07

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:44:33

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:45:04

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:45:30

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:45:54

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:46:13

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:46:41

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:47:10

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:47:43

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:48:09

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:48:39

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:49:04

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:49:34

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:49:56

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:50:30

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:50:53

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:51:28

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:51:51

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 09:52:30

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 09:52:52

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:01:46

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:02:08

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:02:35

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:03:00

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:03:26

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:03:52

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:04:23

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:04:49

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:05:23

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:05:45

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:06:19

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:06:44

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:07:18

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:07:41

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:08:17

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:08:42

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:09:24

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:09:56

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:10:30

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:10:53

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.DEC.2021 11:11:19

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.DEC.2021 11:11:42

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 14.DEC.2021 11:12:11

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 14.DEC.2021 11:12:37