



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:28:51

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:29:23

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:29:51

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:30:16

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:30:39

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:31:04

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:31:33

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:31:55

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:32:18

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:32:43

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:33:08

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:33:34

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:34:06

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:34:31

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:34:54

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:35:25

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:36:03

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:36:32

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:37:02

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:37:27

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:38:03

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:38:25

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:39:01

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:39:30

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:39:59

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:40:25

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:40:56

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:41:25

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:41:57

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:42:25

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:43:04

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:43:23

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:44:01

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:44:30

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 26.JUN.2022 12:45:05


Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 26.JUN.2022 12:45:39




Date: 28.JUN.2022 12:26:16




Date: 28.JUN.2022 12:26:26




Date: 28.JUN.2022 12:26:42




Date: 28.JUN.2022 12:26:52




Date: 28.JUN.2022 12:27:05




Date: 28.JUN.2022 12:27:15




Date: 28.JUN.2022 12:27:33




Date: 28.JUN.2022 12:27:43




Date: 28.JUN.2022 12:27:56




Date: 28.JUN.2022 12:28:06




Date: 28.JUN.2022 12:28:19




Date: 28.JUN.2022 12:28:29




Date: 28.JUN.2022 12:28:47




Date: 28.JUN.2022 12:28:57




Date: 28.JUN.2022 12:29:10




Date: 28.JUN.2022 12:29:20




Date: 28.JUN.2022 12:29:36




Date: 28.JUN.2022 12:29:46




Date: 28.JUN.2022 12:30:01




Date: 28.JUN.2022 12:30:11




Date: 28.JUN.2022 12:30:29




Date: 28.JUN.2022 12:30:39




Date: 28.JUN.2022 12:30:53




Date: 28.JUN.2022 12:31:03




Date: 28.JUN.2022 12:31:21




Date: 28.JUN.2022 12:31:31




Date: 28.JUN.2022 12:31:47




Date: 28.JUN.2022 12:31:57




Date: 28.JUN.2022 12:32:14




Date: 28.JUN.2022 12:32:24




Date: 28.JUN.2022 12:32:44




Date: 28.JUN.2022 12:32:54




Date: 28.JUN.2022 12:33:14



Date: 28.JUN.2022 12:33:24




Date: 28.JUN.2022 12:33:44




Date: 28.JUN.2022 12:33:54

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 26.JUN.2022 18:58:19

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 26.JUN.2022 18:58:48

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 26.JUN.2022 18:59:20

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 26.JUN.2022 18:59:45

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:00:23

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:00:45

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:01:12

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:01:31

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:02:09

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:02:31

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:03:06

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:03:22

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:03:51

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:04:13

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:05:24

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:05:43

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:06:07

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:06:36

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:07:12

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:07:40

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.JUN.2022 19:08:07


Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 26.JUN.2022 19:08:32




Date: 28.JUN.2022 12:34:11



Date: 28.JUN.2022 12:34:21



Date: 28.JUN.2022 12:34:34



Date: 28.JUN.2022 12:34:44