




Please refer to following plots:




Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 12.MAR.2022 11:49:00

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 12.MAR.2022 11:49:27

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 12.MAR.2022 11:49:45

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 12.MAR.2022 11:50:02

Band 2_3 MHz_High_QPSK_RB15#0




Date: 12.MAR.2022 11:50:17

Band 2_3 MHz_High_16QAM_RB15#0




Date: 12.MAR.2022 11:50:46

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 11:51:11

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 11:51:31


Band 2_5 MHz_High_QPSK_RB25#0



Band 2_5 MHz_High_16QAM_RB25#0




Band 2_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 11:52:28

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 11:52:53


Band 2_10 MHz_High_QPSK_RB50#0



Band 2_10 MHz_High_16QAM_RB50#0




Band 2_15 MHz_Low_QPSK_RB75#0




Date: 12.MAR.2022 11:54:17

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 12.MAR.2022 11:54:47

Band 2_15 MHz_High_QPSK_RB75#0




Date: 12.MAR.2022 11:55:17

Band 2_15 MHz_High_16QAM_RB75#0




Date: 12.MAR.2022 11:55:47

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 12.MAR.2022 11:56:18

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 12.MAR.2022 11:56:45

Band 2_20 MHz_High_QPSK_RB100#0




Date: 12.MAR.2022 11:57:18

Band 2_20 MHz_High_16QAM_RB100#0




Date: 12.MAR.2022 11:57:45

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 12.MAR.2022 11:58:07

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 12.MAR.2022 11:58:21

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 12.MAR.2022 11:58:39

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 12.MAR.2022 11:58:59


Band 4_3 MHz_Low_QPSK_RB15#0



Band 4_3 MHz_Low_16QAM_RB15#0




Band 4_3 MHz_High_QPSK_RB15#0




Date: 12.MAR.2022 11:59:52

Band 4_3 MHz_High_16QAM_RB15#0




Date: 12.MAR.2022 12:00:09

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 12.MAR.2022 12:00:22

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 12.MAR.2022 12:00:45

Band 4_5 MHz_High_QPSK_RB25#0




Date: 12.MAR.2022 12:01:06

Band 4_5 MHz_High_16QAM_RB25#0




Date: 12.MAR.2022 12:01:23

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 12.MAR.2022 12:01:55

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 12.MAR.2022 12:02:19


Band 4_10 MHz_High_QPSK_RB50#0



Band 4_10 MHz_High_16QAM_RB50#0




Band 4_15 MHz_Low_QPSK_RB75#0




Date: 12.MAR.2022 12:03:34

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 12.MAR.2022 12:04:00

Band 4_15 MHz_High_QPSK_RB75#0




Date: 12.MAR.2022 12:04:31

Band 4_15 MHz_High_16QAM_RB75#0




Date: 12.MAR.2022 12:05:01

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 12.MAR.2022 12:05:25

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 12.MAR.2022 12:05:58

Band 4_20 MHz_High_QPSK_RB100#0




Date: 12.MAR.2022 12:06:29

Band 4_20 MHz_High_16QAM_RB100#0




Date: 12.MAR.2022 12:06:59

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 12.MAR.2022 12:07:11

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 12.MAR.2022 12:07:28

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 12.MAR.2022 12:07:42

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 12.MAR.2022 12:07:59

Band 5_3 MHz_Low_QPSK_RB15#0



Date: 12.MAR.2022 12:08:18

Band 5_3 MHz_Low_16QAM_RB15#0



Date: 12.MAR.2022 12:08:35