



3MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:32:24

3MHz_Low_QPSK_15@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:31:57

3MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:33:19

3MHz_Low_16QAM_15@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:32:52

3MHz_High_QPSK_1@14




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:34:31

3MHz_High_QPSK_15@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:34:03

3MHz_High_16QAM_1@14




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:35:26

3MHz_High_16QAM_15@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:34:59

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:37:04

5MHz_Low_QPSK_25@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:36:38

5MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:37:55

5MHz_Low_16QAM_25@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:37:30

5MHz_High_QPSK_1@24




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:39:04

5MHz_High_QPSK_25@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:38:18

5MHz_High_16QAM_1@24




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:39:56

5MHz_High_16QAM_25@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:39:30

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:41:57

10MHz_Low_QPSK_50@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:41:20

10MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:43:09

10MHz_Low_16QAM_50@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:42:33

10MHz_High_QPSK_1@49




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:44:38

10MHz_High_QPSK_50@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:44:01

10MHz_High_16QAM_1@49




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:45:50

10MHz_High_16QAM_50@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:45:14

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:48:03

15MHz_Low_QPSK_75@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:47:18

15MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:49:33

15MHz_Low_16QAM_75@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:48:48

15MHz_High_QPSK_1@74




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:51:19

15MHz_High_QPSK_75@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:50:34

15MHz_High_16QAM_1@74




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:52:50

15MHz_High_16QAM_75@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:52:04

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:56:21

20MHz_Low_QPSK_100@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:55:25

20MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:58:13

20MHz_Low_16QAM_100@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:57:17

20MHz_High_QPSK_1@99




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 22:00:20

20MHz_High_QPSK_100@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:59:24

20MHz_High_16QAM_1@99



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 22:02:12


20MHz_High_16QAM_100@0



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 22:01:16


B41_2, Normal

2_5MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:14:41

2_5MHz_Low_QPSK_25@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:14:27

2_5MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:15:09

2_5MHz_Low_16QAM_25@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:14:55

2_5MHz_High_QPSK_1@24




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:15:58

2_5MHz_High_QPSK_25@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:15:44

2_5MHz_High_16QAM_1@24




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:16:26

2_5MHz_High_16QAM_25@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:16:12

2_10MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:18:37

2_10MHz_Low_QPSK_50@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:18:23

2_10MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:19:06

2_10MHz_Low_16QAM_50@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:18:51

2_10MHz_High_QPSK_1@49




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:19:58

2_10MHz_High_QPSK_50@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:19:43

2_10MHz_High_16QAM_1@49




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:20:26

2_10MHz_High_16QAM_50@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:20:12

2_15MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:21:50

2_15MHz_Low_QPSK_75@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:21:36

2_15MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:22:19

2_15MHz_Low_16QAM_75@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 21:22:04

2_15MHz_High_QPSK_1@74




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:23:09

2_15MHz_High_QPSK_75@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:22:54

2_15MHz_High_16QAM_1@74




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:23:37

2_15MHz_High_16QAM_75@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:23:23

2_20MHz_Low_QPSK_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:25:00

2_20MHz_Low_QPSK_100@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:24:46

2_20MHz_Low_16QAM_1@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:25:29

2_20MHz_Low_16QAM_100@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:25:14

2_20MHz_High_QPSK_1@99




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:26:17

2_20MHz_High_QPSK_100@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:26:03

2_20MHz_High_16QAM_1@99



ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:26:46

2_20MHz_High_16QAM_100@0




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 21:26:32

Spurious Emissions at Antenna Terminal


FCC Part 22H

B5, Normal


1.4MHz_Low_QPSK_1@0 -25.84dBm




1.4MHz_Low_QPSK_6@0 -25.10dBm




1.4MHz_Middle_QPSK_1@0 -24.87dBm




1.4MHz_Middle_QPSK_6@0 -25.24dBm




1.4MHz_High_QPSK_1@0 -24.94dBm



1.4MHz_High_QPSK_6@0 -24.91dBm




3MHz_Low_QPSK_1@0 -25.71dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:51:56

3MHz_Low_QPSK_15@0 -25.15dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:52:12

3MHz_Middle_QPSK_1@0 -25.21dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:52:30

3MHz_Middle_QPSK_15@0 -25.63dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:52:46

3MHz_High_QPSK_1@0 -24.93dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:53:03

3MHz_High_QPSK_15@0 -24.97dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:53:19

5MHz_Low_QPSK_1@0 -25.82dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:54:04

5MHz_Low_QPSK_25@0 -25.56dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:54:21

5MHz_Middle_QPSK_1@0 -25.36dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:54:38

5MHz_Middle_QPSK_25@0 -24.97dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:54:55

5MHz_High_QPSK_1@0 -25.91dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:55:12

5MHz_High_QPSK_25@0 -25.73dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:55:28

10MHz_Low_QPSK_1@0 -25.67dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:56:15

10MHz_Low_QPSK_50@0 -25.51dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:56:31

10MHz_Middle_QPSK_1@0 -25.02dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:56:49

10MHz_Middle_QPSK_50@0 -24.72dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:57:06

10MHz_High_QPSK_1@0 -24.87dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:57:22

10MHz_High_QPSK_50@0 -24.71dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:57:39

FCC Part 24E


B2 , Normal

1.4MHz_Low_QPSK_1@0 -24.33dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:21:28

1.4MHz_Low_QPSK_6@0 -24.74dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:21:46

1.4MHz_Middle_QPSK_1@0 -23.86dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:22:04

1.4MHz_Middle_QPSK_6@0 -24.54dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:22:22

1.4MHz_High_QPSK_1@0 -24.85dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:22:41

1.4MHz_High_QPSK_6@0 -24.47dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:23:00

3MHz_Low_QPSK_1@0 -24.29dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:23:50

3MHz_Low_QPSK_15@0 -24.75dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:24:09

3MHz_Middle_QPSK_1@0 -24.26dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:24:28

3MHz_Middle_QPSK_15@0 -24.63dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:24:48

3MHz_High_QPSK_1@0 -24.35dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:25:07

3MHz_High_QPSK_15@0 -25.05dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:25:16

5MHz_Low_QPSK_1@0 -24.45dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:26:16

5MHz_Low_QPSK_25@0 -24.78dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:26:35

5MHz_Middle_QPSK_1@0 -24.93dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:26:55

5MHz_Middle_QPSK_25@0 -24.50dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:27:15

5MHz_High_QPSK_1@0 -24.07dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:27:34

5MHz_High_QPSK_25@0 -24.51dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:27:53

10MHz_Low_QPSK_1@0 -25.00dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:28:50

10MHz_Low_QPSK_50@0 -24.52dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:29:09

10MHz_Middle_QPSK_1@0 -24.26dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:29:28

10MHz_Middle_QPSK_50@0 -24.47dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:29:47

10MHz_High_QPSK_1@0 -24.66dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:30:06

10MHz_High_QPSK_50@0 -24.93dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:30:25