



3MHz_Low_QPSK_1@0 -23.33dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:52:44

3MHz_Low_QPSK_15@0 -24.70dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:53:05

3MHz_Middle_QPSK_1@0 -24.26dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:53:27

3MHz_Middle_QPSK_15@0 -24.05dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:53:49

3MHz_High_QPSK_1@0 -24.47dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:54:12

3MHz_High_QPSK_15@0 -24.56dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:54:34

5MHz_Low_QPSK_1@0 -24.22dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:55:26

5MHz_Low_QPSK_25@0 -23.85dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:55:49

5MHz_Middle_QPSK_1@0 -23.94dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:56:12

5MHz_Middle_QPSK_25@0 -23.55dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:56:34

5MHz_High_QPSK_1@0 -24.39dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:56:56

5MHz_High_QPSK_25@0 -24.29dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:57:19

10MHz_Low_QPSK_1@0 -24.31dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:58:12

10MHz_Low_QPSK_50@0 -23.35dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:58:34

10MHz_Middle_QPSK_1@0 -24.75dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:58:57

10MHz_Middle_QPSK_50@0 -23.32dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:59:20

10MHz_High_QPSK_1@0 -24.46dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:59:42

10MHz_High_QPSK_50@0 -24.55dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 16:00:05

15MHz_Low_QPSK_1@0 -24.93dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 16:00:58

15MHz_Low_QPSK_75@0 -24.64dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 16:01:20

15MHz_Middle_QPSK_1@0 -24.16dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 16:01:43

15MHz_Middle_QPSK_75@0 -24.93dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 16:02:05

15MHz_High_QPSK_1@0 -24.02dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 16:02:27

15MHz_High_QPSK_75@0 -24.46dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 16:02:50


20MHz_Low_QPSK_1@0 -24.11dBm




20MHz_Low_QPSK_100@0 -23.84dBm




20MHz_Middle_QPSK_1@0 -24.15dBm




20MHz_Middle_QPSK_100@0 -24.78dBm



20MHz_High_QPSK_1@0 -24.35dBm




20MHz_High_QPSK_100@0 -24.09dBm




B41_2, Normal

2_5MHz_Low_QPSK_1@0 -35.07dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:38:24

2_5MHz_Low_QPSK_25@0 -34.65dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:38:47

2_5MHz_Middle_QPSK_1@0 -33.92dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:39:11

2_5MHz_Middle_QPSK_25@0 -35.13dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:39:35

2_5MHz_High_QPSK_1@0 -34.63dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:39:59

2_5MHz_High_QPSK_25@0 -34.78dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:40:23

2_10MHz_Low_QPSK_1@0 -33.88dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:42:00

2_10MHz_Low_QPSK_50@0 -35.13dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:42:24

2_10MHz_Middle_QPSK_1@0 -34.19dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:42:48

2_10MHz_Middle_QPSK_50@0 -34.44dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:43:10

2_10MHz_High_QPSK_1@0 -34.52dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:43:33

2_10MHz_High_QPSK_50@0 -34.49dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:43:55

2_15MHz_Low_QPSK_1@0 -34.55dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:44:47

2_15MHz_Low_QPSK_75@0 -34.83dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:45:10

2_15MHz_Middle_QPSK_1@0 -34.52dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:45:32

2_15MHz_Middle_QPSK_75@0 -34.86dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:45:55

2_15MHz_High_QPSK_1@0 -34.66dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:46:17

2_15MHz_High_QPSK_75@0 -34.79dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:46:39

2_20MHz_Low_QPSK_1@0 -34.59dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:47:36

2_20MHz_Low_QPSK_100@0 -34.66dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:47:58

2_20MHz_Middle_QPSK_1@0 -34.80dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:48:20

2_20MHz_Middle_QPSK_100@0 -34.50dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:48:42

2_20MHz_High_QPSK_1@0 -34.94dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:49:04

2_20MHz_High_QPSK_100@0 -34.67dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:49:26