

**Test Information:**

|                    |                    |                     |                       |
|--------------------|--------------------|---------------------|-----------------------|
| <b>Serial No.:</b> | 2Q03-1             | <b>Test Date:</b>   | 2024/08/18~2024/08/19 |
| <b>Test Site:</b>  | RF                 | <b>Test Mode:</b>   | Transmitting          |
| <b>Tester:</b>     | Kangfumaster Liang | <b>Test Result:</b> | Pass                  |

**Environmental Conditions:**

|                              |       |                                  |       |                               |     |
|------------------------------|-------|----------------------------------|-------|-------------------------------|-----|
| <b>Temperature:</b><br>(°C): | 25-26 | <b>Relative Humidity:</b><br>(%) | 45-50 | <b>ATM Pressure:</b><br>(kPa) | 101 |
|------------------------------|-------|----------------------------------|-------|-------------------------------|-----|

**Frequency stability**  
**FCC Part 96**

**n77\_2**

| Mode  | F_L (MHz) | F_H (MHz) | Limit (MHz) | Result |
|---|-----------|-----------|-------------|--------|
| 10MHz_30kHz_3555,3695MHz_DFT-sQPSK_RB24@0     | 3550.164  | 3699.877  | 3550~3700   | Pass   |
| 15MHz_30kHz_3557.5,3692.5MHz_DFT-sQPSK_RB36@0 | 3550.067  | 3699.841  | 3550~3700   | Pass   |
| 20MHz_30kHz_3560,3690MHz_DFT-sQPSK_RB50@0     | 3550.037  | 3699.916  | 3550~3700   | Pass   |
| 30MHz_30kHz_3565,3685MHz_DFT-sQPSK_RB78@0     | 3550.183  | 3699.998  | 3550~3700   | Pass   |
| 40MHz_30kHz_3570,3680MHz_DFT-sQPSK_RB100@0    | 3550.128  | 3699.871  | 3550~3700   | Pass   |
| 50MHz_30kHz_3575,3675MHz_DFT-sQPSK_RB128@0    | 3550.109  | 3699.888  | 3550~3700   | Pass   |
| 60MHz_30kHz_3580,3670MHz_DFT-sQPSK_RB162@0    | 3550.181  | 3699.965  | 3550~3700   | Pass   |
| 70MHz_30kHz_3585,3665MHz_DFT-sQPSK_RB180@0    | 3550.067  | 3699.809  | 3550~3700   | Pass   |
| 80MHz_30kHz_3590,3660MHz_DFT-sQPSK_RB216@0    | 3550.016  | 3699.915  | 3550~3700   | Pass   |
| 90MHz_30kHz_3595,3655MHz_DFT-sQPSK_RB243@0    | 3550.174  | 3699.943  | 3550~3700   | Pass   |
| 100MHz_30kHz_3600,3650MHz_DFT-sQPSK_RB270@0   | 3550.054  | 3699.841  | 3550~3700   | Pass   |

**n78\_2**

| Mode  | F_L (MHz) | F_H (MHz) | Limit (MHz) | Result |
|---|-----------|-----------|-------------|--------|
| 10MHz_30kHz_3555,3695MHz_DFT-sQPSK_RB24@0     | 3550.088  | 3699.918  | 3550~3700   | Pass   |
| 15MHz_30kHz_3557.5,3692.5MHz_DFT-sQPSK_RB36@0 | 3550.095  | 3699.898  | 3550~3700   | Pass   |
| 20MHz_30kHz_3560,3690MHz_DFT-sQPSK_RB50@0     | 3550.075  | 3699.827  | 3550~3700   | Pass   |
| 30MHz_30kHz_3565,3685MHz_DFT-sQPSK_RB78@0     | 3550.028  | 3699.974  | 3550~3700   | Pass   |
| 40MHz_30kHz_3570,3680MHz_DFT-sQPSK_RB100@0    | 3550.194  | 3699.876  | 3550~3700   | Pass   |
| 50MHz_30kHz_3575,3675MHz_DFT-sQPSK_RB128@0    | 3550.023  | 3699.828  | 3550~3700   | Pass   |
| 60MHz_30kHz_3580,3670MHz_DFT-sQPSK_RB162@0    | 3550.002  | 3699.892  | 3550~3700   | Pass   |
| 70MHz_30kHz_3585,3665MHz_DFT-sQPSK_RB180@0    | 3550.109  | 3699.982  | 3550~3700   | Pass   |
| 80MHz_30kHz_3590,3660MHz_DFT-sQPSK_RB216@0    | 3550.026  | 3699.833  | 3550~3700   | Pass   |
| 90MHz_30kHz_3595,3655MHz_DFT-sQPSK_RB243@0    | 3550.007  | 3699.909  | 3550~3700   | Pass   |
| 100MHz_30kHz_3600,3650MHz_DFT-sQPSK_RB270@0   | 3550.138  | 3699.831  | 3550~3700   | Pass   |