


# INTERTEK TESTING SERVICE

Report No.: 15080418HKG-001

## Equipment Photographs

**(Internal)**



---

FCC ID: 2AE3ABTM023PC



IC: 20421-BTM023PC

# INTERTEK TESTING SERVICE

Report No.: 15080418HKG-001

## Equipment Photographs

(Internal)



---

FCC ID: 2AE3ABTM023PC



IC: 20421-BTM023PC

# INTERTEK TESTING SERVICE

Report No.: 15080418HKG-001

## Equipment Photographs

(Internal)



---

FCC ID: 2AE3ABTM023PC



IC: 20421-BTM023PC

# INTERTEK TESTING SERVICE

Report No.: 15080418HKG-001

## Equipment Photographs

(Internal)



---

FCC ID: 2AE3ABTM023PC

IC: 20421-BTM023PC