

When using WWAN communication mode, WiFi function will be off by self check through internal circuit. So this device (FCC ID: 2AEHZCOOL2G) is not capable of connecting in a 'Wireless Hotspot' configuration.

Signature:



Name: ***Joe zhou***

Title: Manager

Time: 29. 04, 2015