







NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID1_N
S_01_0.009_0.15_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID1_N
S_01_0.15_30_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID1_N
S_01_30_1000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID1_N
S_01_1000_3000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID1_N
S_01_3000_6000_#1







NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID1_N
S_01_6000_26000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID1_N
S_01_26000_40000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID2_N
S_01_0.009_0.15_#1


NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID2_N
S_01_0.15_30_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID2_N
S_01_30_1000_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID2_N
S_01_1000_3000_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID2_N
S_01_3000_6000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID2_N
S_01_6000_26000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID2_N
S_01_26000_40000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID4_N
S_01_0.009_0.15_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID4_N
S_01_0.15_30_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID4_N
S_01_30_1000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID4_N
S_01_1000_3000_#1







NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID4_N
S_01_3000_6000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID4_N
S_01_6000_26000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID5_N
S_01_1000_3000_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID5_N
S_01_3000_6000_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID5_N
S_01_6000_26000_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+70_M+H_TID5_N
S_01_26000_40000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID1_NS_01_0.009_0.15_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID1_NS_01_0.15_30_#1



NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID1_NS_01_30_1000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID1_NS_01_1000_3000_#1




04:10:10 PM 07/04/2024

NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID1_NS_01_3000_6000_#1




04:10:19 PM 07/04/2024

NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID1_NS_01_6000_26000_#1





04:10:28 PM 07/04/2024

NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID1_NS_01_26000_40000_#1






04:10:43 PM 07/04/2024

NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID2_NS_01_0.009_0.15_#1


NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID2_NS
_01_0.15_30_#1

NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID2_NS
_01_30_1000_#1


NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID2_NS
_01_1000_3000_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID2_NS
_01_3000_6000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID2_NS_01_6000_26000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID2_NS_01_26000_40000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID4_NS_01_0.009_0.15_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID4_NS_01_0.15_30_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID4_NS_01_30_1000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID4_NS_01_1000_3000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID4_NS_01_3000_6000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID4_NS_01_6000_26000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID4_NS_01_26000_40000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID5_NS_01_0.009_0.15_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID5_NS_01_0.15_30_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID5_NS_01_30_1000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID5_NS_01_1000_3000_#1






NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID5_NS_01_3000_6000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID5_NS_01_6000_26000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+L_TID5_NS_01_26000_40000_#1


NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID1_N
S_01_0.009_0.15_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID1_N
S_01_0.15_30_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID1_N
S_01_30_1000_#1NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID1_N
S_01_1000_3000_#1




04:14:31 PM 07/04/2024

NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID1_N
S_01_3000_6000_#1

04:14:40 PM 07/04/2024


NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID1_N
S_01_6000_26000_#1

04:14:49 PM 07/04/2024


NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID1_N
S_01_26000_40000_#1

04:15:04 PM 07/04/2024


NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID2_N
S_01_0.009_0.15_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID2_N
S_01_0.15_30_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID2_N
S_01_30_1000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID2_N
S_01_1000_3000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID2_N
S_01_3000_6000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID2_N
S_01_6000_26000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID2_N
S_01_26000_40000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID4_N
S_01_0.009_0.15_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID4_N
S_01_0.15_30_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID4_N
S_01_30_1000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID4_N
S_01_1000_3000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID4_N
S_01_3000_6000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID4_N
S_01_6000_26000_#1




NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID4_N
S_01_26000_40000_#1



NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID5_N
S_01_0.009_0.15_#1



NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID5_N
S_01_0.15_30_#1



NTNV_DC_26A_n78A-3450-3550_PC3_30_5+80_M+M_TID5_N
S_01_30_1000_#1