

Harsco Rail
2401 Edmund Road
Box 20
W. Columbia, SC 29171-0020
Phone: 803.822.9160
Fax: 803.822.8107
Web: www.harscorail.com



06/05/2019

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Re: Applicant: Harsco Rail, a division of Harsco Corporation
FCC ID: 2AEO5-XBPSX
Part 2.933(b) Change in Identification of Equipment

Harsco Rail requests a change in identification of a currently certified device under Part 2.933(b).

The original equipment identification is FCC ID: MCQ-XBPSX.
The original grant for Digi International was issued on 12/22/2015.

The original test data filed by Digi International continues to be representative of the newly identified device. There are no changes to the hardware or software.

This change in identification is requested for the newly identified device, FCC ID: 2AEO5-XBPSX, which is physically and electrically identical as defined by Part 2.907, to the originally approved module.

Photographs as required under Part 2.933(5) and FCC ID label are submitted with this request.

Please let us know if you might require anything further to assist with your review of this Change in Identification of Equipment.

A handwritten signature in blue ink, appearing to read "James Resio", with a long horizontal flourish extending to the right.

James Resio
VP Protran Technology: A Harsco Rail Company