

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change  
2AEP2-THAWK1  
20168-THAWK1  
20-0112  
April 17, 2020  
Headsight Inc  
HT5200 and HT5230



**Figure 1. Top View**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change  
2AEP2-THAWK1  
20168-THAWK1  
20-0112  
April 17, 2020  
Headsight Inc  
HT5200 and HT5230



**Figure 2. Side View**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change  
2AEP2-THAWK1  
20168-THAWK1  
20-0112  
April 17, 2020  
Headsight Inc  
HT5200 and HT5230



**Figure 3. Bottom View**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change  
2AEP2-THAWK1  
20168-THAWK1  
20-0112  
April 17, 2020  
Headsight Inc  
HT5200 and HT5230



1.

**Figure 4. EUT without USB Access Port (HT5200)**

US Tech Test Report:  
FCC ID:  
IC:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15/ RSS 220 Class 2 Permissive Change  
2AEP2-THAWK1  
20168-THAWK1  
20-0112  
April 17, 2020  
Headsight Inc  
HT5200 and HT5230



**Figure 5. EUT with USB Access Port (HT5230)**