

Appendix for N78 (3450-3550MHz)

Product Name: Smart phone

Model No: Black 5

Appendix A: Average Power Output Data for SA

Test Result

Band	SCS	Bandwidth	Modulation	Channel	RB Config	Power (dBm)	Power Class	Verdict
N78-3450-3550	30	10	DFT-QPSK	L	Outer_Full	25.09	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	L	Inner_Full	26.13	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	L	Edge_1RB_Left	23.05	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	L	Edge_1RB_Right	23.03	PC2	PASS
N78-3450-3550	30	10	DFT-16QAM	L	Outer_Full	24.02	PC2	PASS
N78-3450-3550	30	10	DFT-16QAM	L	Inner_Full	24.88	PC2	PASS
N78-3450-3550	30	10	DFT-16QAM	L	Edge_1RB_Left	23.11	PC2	PASS
N78-3450-3550	30	10	DFT-16QAM	L	Edge_1RB_Right	23.07	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	M	Outer_Full	25.02	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	M	Inner_Full	26.02	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	M	Edge_1RB_Left	22.99	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	M	Edge_1RB_Right	22.88	PC2	PASS
N78-3450-3550	30	10	DFT-16QAM	M	Outer_Full	24.15	PC2	PASS
N78-3450-3550	30	10	DFT-16QAM	M	Inner_Full	25.04	PC2	PASS
N78-3450-3550	30	10	DFT-16QAM	M	Edge_1RB_Left	23.22	PC2	PASS
N78-3450-3550	30	10	DFT-16QAM	M	Edge_1RB_Right	23.17	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	H	Outer_Full	25.01	PC2	PASS
N78-3450-3550	30	10	DFT-QPSK	H	Inner_Full	25.89	PC2	PASS

N78-3450 -3550	30	10	DFT-QPSK	H	Edge_1RB_Left	22.65	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Edge_1RB_Right	22.81	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Outer_Full	24.09	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Inner_Full	24.94	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Edge_1RB_Left	22.56	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Edge_1RB_Right	22.74	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Outer_Full	25.32	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Inner_Full	26.09	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Edge_1RB_Left	22.85	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Edge_1RB_Right	22.78	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Outer_Full	24.24	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Inner_Full	25.18	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Edge_1RB_Left	22.62	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Edge_1RB_Right	22.63	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Outer_Full	25.15	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Inner_Full	26.07	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Edge_1RB_Left	22.99	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Edge_1RB_Right	22.93	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Outer_Full	24.15	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Inner_Full	25.04	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Edge_1RB_Left	23.03	PC2	PASS
N78-3450	30	15	DFT-16QAM	M	Edge_1RB_Right	23.03	PC2	PASS

-3550								
N78-3450 -3550	30	15	DFT-QPSK	H	Outer_Full	25.04	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Inner_Full	25.91	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Edge_1RB_Left	22.67	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Edge_1RB_Right	22.79	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Outer_Full	24.00	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Inner_Full	25.01	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Edge_1RB_Left	23.03	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Edge_1RB_Right	23.17	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Outer_Full	25.24	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Inner_Full	26.18	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Edge_1RB_Left	22.96	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Edge_1RB_Right	23.00	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Outer_Full	24.24	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Inner_Full	25.06	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Edge_1RB_Left	22.87	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Edge_1RB_Right	22.92	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Outer_Full	25.19	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Inner_Full	26.17	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Edge_1RB_Left	23.09	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Edge_1RB_Right	22.99	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Outer_Full	24.22	PC2	PASS

N78-3450 -3550	30	20	DFT-16QAM	M	Inner_Full	25.15	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Edge_1RB_Left	22.71	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Edge_1RB_Right	22.63	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Outer_Full	25.00	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Inner_Full	25.90	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Edge_1RB_Left	22.67	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Edge_1RB_Right	22.77	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Outer_Full	23.98	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Inner_Full	24.89	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Edge_1RB_Left	22.90	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Edge_1RB_Right	22.98	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Outer_Full	25.32	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Inner_Full	26.36	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Edge_1RB_Left	22.84	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Edge_1RB_Right	22.99	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Outer_Full	24.37	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Inner_Full	25.41	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Edge_1RB_Left	22.81	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Edge_1RB_Right	22.99	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Outer_Full	25.33	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Inner_Full	26.22	PC2	PASS
N78-3450	30	40	DFT-QPSK	M	Edge_1RB_Left	23.09	PC2	PASS

-3550								
N78-3450 -3550	30	40	DFT-QPSK	M	Edge_1RB_Right	22.90	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Outer_Full	24.31	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Inner_Full	25.19	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Edge_1RB_Left	23.05	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Edge_1RB_Right	22.89	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Outer_Full	25.18	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Inner_Full	26.02	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Edge_1RB_Left	22.77	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Edge_1RB_Right	22.71	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Outer_Full	24.12	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Inner_Full	25.04	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Edge_1RB_Left	22.88	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Edge_1RB_Right	22.80	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Outer_Full	25.37	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Inner_Full	26.37	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Edge_1RB_Left	22.91	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Edge_1RB_Right	22.84	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Outer_Full	24.37	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Inner_Full	25.33	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Edge_1RB_Left	22.88	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Edge_1RB_Right	22.78	PC2	PASS

N78-3450 -3550	30	50	DFT-QPSK	M	Outer_Full	25.33	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Inner_Full	26.29	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Edge_1RB_Left	23.10	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Edge_1RB_Right	22.95	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Outer_Full	24.34	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Inner_Full	25.30	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Edge_1RB_Left	22.93	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Edge_1RB_Right	22.79	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Outer_Full	25.16	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Inner_Full	26.16	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Edge_1RB_Left	22.69	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Edge_1RB_Right	22.69	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Outer_Full	24.16	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Inner_Full	25.25	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Edge_1RB_Left	22.95	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Edge_1RB_Right	22.94	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Outer_Full	25.26	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Inner_Full	26.31	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Edge_1RB_Left	22.84	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Edge_1RB_Right	22.82	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Outer_Full	24.37	PC2	PASS
N78-3450	30	60	DFT-16QAM	L	Inner_Full	25.38	PC2	PASS

-3550								
N78-3450 -3550	30	60	DFT-16QAM	L	Edge_1RB_Left	22.67	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Edge_1RB_Right	22.61	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Outer_Full	25.32	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Inner_Full	26.24	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Edge_1RB_Left	22.92	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Edge_1RB_Right	22.77	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Outer_Full	24.28	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Inner_Full	25.27	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Edge_1RB_Left	22.87	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Edge_1RB_Right	22.74	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Outer_Full	25.17	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Inner_Full	26.10	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Edge_1RB_Left	22.85	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Edge_1RB_Right	22.72	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Outer_Full	24.21	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Inner_Full	25.18	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Edge_1RB_Left	23.13	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Edge_1RB_Right	23.03	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Outer_Full	25.24	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Inner_Full	26.36	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Edge_1RB_Left	22.98	PC2	PASS

N78-3450 -3550	30	70	DFT-QPSK	L	Edge_1RB_Right	22.96	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Outer_Full	24.32	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Inner_Full	25.33	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Edge_1RB_Left	22.94	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Edge_1RB_Right	22.94	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Outer_Full	25.31	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Inner_Full	26.25	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Edge_1RB_Left	22.92	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Edge_1RB_Right	22.67	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Outer_Full	24.27	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Inner_Full	25.29	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Edge_1RB_Left	22.76	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Edge_1RB_Right	22.54	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Outer_Full	25.21	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Inner_Full	26.16	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Edge_1RB_Left	23.06	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Edge_1RB_Right	22.75	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Outer_Full	24.14	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Inner_Full	25.17	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Edge_1RB_Left	23.29	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Edge_1RB_Right	23.02	PC2	PASS
N78-3450	30	80	DFT-QPSK	L	Outer_Full	25.29	PC2	PASS

-3550								
N78-3450 -3550	30	80	DFT-QPSK	L	Inner_Full	26.26	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Edge_1RB_Left	22.95	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Edge_1RB_Right	22.80	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Outer_Full	24.37	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Inner_Full	25.30	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Edge_1RB_Left	22.81	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Edge_1RB_Right	22.65	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Outer_Full	25.30	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Inner_Full	26.26	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Edge_1RB_Left	22.92	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Edge_1RB_Right	22.72	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Outer_Full	24.45	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Inner_Full	25.31	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Edge_1RB_Left	22.92	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Edge_1RB_Right	22.71	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Outer_Full	25.23	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Inner_Full	26.20	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Edge_1RB_Left	22.94	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Edge_1RB_Right	22.82	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Outer_Full	24.24	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Inner_Full	25.21	PC2	PASS

N78-3450 -3550	30	80	DFT-16QAM	H	Edge_1RB_Left	23.19	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Edge_1RB_Right	23.05	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Outer_Full	25.25	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Inner_Full	26.29	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Edge_1RB_Left	22.85	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Edge_1RB_Right	22.61	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Outer_Full	24.29	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Inner_Full	25.34	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Edge_1RB_Left	22.84	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Edge_1RB_Right	22.60	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Outer_Full	25.28	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Inner_Full	26.31	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Edge_1RB_Left	22.83	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Edge_1RB_Right	22.73	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Outer_Full	24.31	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Inner_Full	25.25	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Edge_1RB_Left	22.71	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Edge_1RB_Right	22.55	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Outer_Full	25.25	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Inner_Full	26.26	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Edge_1RB_Left	22.76	PC2	PASS
N78-3450	30	90	DFT-QPSK	H	Edge_1RB_Right	22.72	PC2	PASS

-3550								
N78-3450 -3550	30	90	DFT-16QAM	H	Outer_Full	24.24	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Inner_Full	25.30	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Edge_1RB_Left	22.93	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Edge_1RB_Right	22.96	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Outer_Full	25.32	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Inner_Full	26.33	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Edge_1RB_Left	22.82	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Edge_1RB_Right	22.70	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Outer_Full	24.31	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Inner_Full	25.36	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Edge_1RB_Left	22.62	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Edge_1RB_Right	22.49	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Outer_Full	25.24	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Inner_Full	26.34	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Edge_1RB_Left	22.77	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Edge_1RB_Right	22.68	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Outer_Full	24.32	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Inner_Full	25.33	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Edge_1RB_Left	22.61	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Edge_1RB_Right	22.50	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Outer_Full	25.37	PC2	PASS

N78-3450 -3550	30	100	DFT-QPSK	H	Inner_Full	26.38	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Edge_1RB_Left	22.82	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Edge_1RB_Right	22.68	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Outer_Full	24.32	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Inner_Full	25.33	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Edge_1RB_Left	22.61	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Edge_1RB_Right	22.54	PC2	PASS

Hotspot ON

Band	SCS	Bandwidth	Modulation	Channel	RB Config	Power (dBm)	Power Class	Verdict
N78-3450 -3550	30	10	DFT-QPSK	L	Outer_Full	21.38	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Inner_Full	21.54	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Edge_1RB_Left	21.74	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Edge_1RB_Right	21.72	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Outer_Full	21.31	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Inner_Full	21.29	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Edge_1RB_Left	21.73	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Edge_1RB_Right	21.72	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Outer_Full	21.44	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Inner_Full	21.35	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Edge_1RB_Left	21.63	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Edge_1RB_Right	21.51	PC2	PASS

N78-3450 -3550	30	10	DFT-16QAM	M	Outer_Full	21.37	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Inner_Full	21.35	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Edge_1RB_Left	21.84	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Edge_1RB_Right	21.75	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Outer_Full	21.28	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Inner_Full	21.29	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Edge_1RB_Left	21.35	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Edge_1RB_Right	21.49	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Outer_Full	21.19	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Inner_Full	21.26	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Edge_1RB_Left	21.24	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Edge_1RB_Right	21.43	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Outer_Full	21.45	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Inner_Full	21.47	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Edge_1RB_Left	21.46	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Edge_1RB_Right	21.43	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Outer_Full	21.56	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Inner_Full	21.42	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Edge_1RB_Left	21.28	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Edge_1RB_Right	21.23	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Outer_Full	21.51	PC2	PASS
N78-3450	30	15	DFT-QPSK	M	Inner_Full	21.42	PC2	PASS

-3550								
N78-3450 -3550	30	15	DFT-QPSK	M	Edge_1RB_Left	21.34	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Edge_1RB_Right	21.26	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Outer_Full	21.45	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Inner_Full	21.44	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Edge_1RB_Left	21.67	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Edge_1RB_Right	21.62	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Outer_Full	21.37	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Inner_Full	21.27	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Edge_1RB_Left	21.34	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Edge_1RB_Right	21.53	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Outer_Full	21.20	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Inner_Full	21.24	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Edge_1RB_Left	21.04	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Edge_1RB_Right	21.24	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Outer_Full	21.42	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Inner_Full	21.53	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Edge_1RB_Left	21.58	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Edge_1RB_Right	21.61	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Outer_Full	21.41	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Inner_Full	21.39	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Edge_1RB_Left	21.55	PC2	PASS

N78-3450 -3550	30	20	DFT-16QAM	L	Edge_1RB_Right	21.55	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Outer_Full	21.45	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Inner_Full	21.45	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Edge_1RB_Left	21.59	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Edge_1RB_Right	21.51	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Outer_Full	21.39	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Inner_Full	21.39	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Edge_1RB_Left	22.03	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Edge_1RB_Right	21.89	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Outer_Full	21.32	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Inner_Full	21.26	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Edge_1RB_Left	21.39	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Edge_1RB_Right	21.58	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Outer_Full	21.26	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Inner_Full	21.18	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Edge_1RB_Left	21.33	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Edge_1RB_Right	21.49	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Outer_Full	21.50	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Inner_Full	21.54	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Edge_1RB_Left	21.45	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Edge_1RB_Right	21.67	PC2	PASS
N78-3450	30	40	DFT-16QAM	L	Outer_Full	21.43	PC2	PASS

-3550								
N78-3450 -3550	30	40	DFT-16QAM	L	Inner_Full	21.52	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Edge_1RB_Left	21.38	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Edge_1RB_Right	21.56	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Outer_Full	21.54	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Inner_Full	21.45	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Edge_1RB_Left	21.81	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Edge_1RB_Right	21.71	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Outer_Full	21.53	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Inner_Full	21.49	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Edge_1RB_Left	22.01	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Edge_1RB_Right	21.96	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Outer_Full	21.35	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Inner_Full	21.32	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Edge_1RB_Left	21.51	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Edge_1RB_Right	21.47	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Outer_Full	21.21	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Inner_Full	21.26	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Edge_1RB_Left	21.20	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Edge_1RB_Right	21.06	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Outer_Full	21.51	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Inner_Full	21.58	PC2	PASS

N78-3450 -3550	30	50	DFT-QPSK	L	Edge_1RB_Left	21.50	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Edge_1RB_Right	21.51	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Outer_Full	21.47	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Inner_Full	21.53	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Edge_1RB_Left	21.48	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Edge_1RB_Right	21.43	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Outer_Full	21.59	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Inner_Full	21.56	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Edge_1RB_Left	21.78	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Edge_1RB_Right	21.64	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Outer_Full	21.61	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Inner_Full	21.50	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Edge_1RB_Left	21.97	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Edge_1RB_Right	21.92	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Outer_Full	21.35	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Inner_Full	21.42	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Edge_1RB_Left	21.50	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Edge_1RB_Right	21.56	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Outer_Full	21.29	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Inner_Full	21.31	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Edge_1RB_Left	21.35	PC2	PASS
N78-3450	30	50	DFT-16QAM	H	Edge_1RB_Right	21.40	PC2	PASS

-3550								
N78-3450 -3550	30	60	DFT-QPSK	L	Outer_Full	21.52	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Inner_Full	21.63	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Edge_1RB_Left	21.43	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Edge_1RB_Right	21.31	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Outer_Full	21.48	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Inner_Full	21.60	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Edge_1RB_Left	21.23	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Edge_1RB_Right	21.24	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Outer_Full	21.54	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Inner_Full	21.51	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Edge_1RB_Left	21.42	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Edge_1RB_Right	21.32	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Outer_Full	21.49	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Inner_Full	21.42	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Edge_1RB_Left	21.61	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Edge_1RB_Right	21.60	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Outer_Full	21.39	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Inner_Full	21.49	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Edge_1RB_Left	21.53	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Edge_1RB_Right	21.42	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Outer_Full	21.34	PC2	PASS

N78-3450 -3550	30	60	DFT-16QAM	H	Inner_Full	21.43	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Edge_1RB_Left	21.30	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Edge_1RB_Right	21.24	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Outer_Full	21.62	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Inner_Full	21.65	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Edge_1RB_Left	21.62	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Edge_1RB_Right	21.62	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Outer_Full	21.56	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Inner_Full	21.64	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Edge_1RB_Left	21.60	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Edge_1RB_Right	21.61	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Outer_Full	21.64	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Inner_Full	21.63	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Edge_1RB_Left	21.54	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Edge_1RB_Right	21.33	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Outer_Full	21.60	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Inner_Full	21.57	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Edge_1RB_Left	21.85	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Edge_1RB_Right	21.57	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Outer_Full	21.57	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Inner_Full	21.58	PC2	PASS
N78-3450	30	70	DFT-QPSK	H	Edge_1RB_Left	21.86	PC2	PASS

-3550								
N78-3450 -3550	30	70	DFT-QPSK	H	Edge_1RB_Right	21.62	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Outer_Full	21.47	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Inner_Full	21.46	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Edge_1RB_Left	21.75	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Edge_1RB_Right	21.48	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Outer_Full	21.63	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Inner_Full	21.69	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Edge_1RB_Left	21.57	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Edge_1RB_Right	21.45	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Outer_Full	21.57	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Inner_Full	21.66	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Edge_1RB_Left	21.44	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Edge_1RB_Right	21.28	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Outer_Full	21.60	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Inner_Full	21.65	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Edge_1RB_Left	21.51	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Edge_1RB_Right	21.30	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Outer_Full	21.55	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Inner_Full	21.57	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Edge_1RB_Left	21.70	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Edge_1RB_Right	21.55	PC2	PASS

N78-3450 -3550	30	80	DFT-QPSK	H	Outer_Full	21.52	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Inner_Full	21.55	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Edge_1RB_Left	21.57	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Edge_1RB_Right	21.50	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Outer_Full	21.51	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Inner_Full	21.49	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Edge_1RB_Left	21.34	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Edge_1RB_Right	21.32	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Outer_Full	21.54	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Inner_Full	21.64	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Edge_1RB_Left	21.51	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Edge_1RB_Right	21.31	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Outer_Full	21.53	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Inner_Full	21.66	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Edge_1RB_Left	21.48	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Edge_1RB_Right	21.31	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Outer_Full	21.55	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Inner_Full	21.65	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Edge_1RB_Left	21.52	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Edge_1RB_Right	21.34	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Outer_Full	21.59	PC2	PASS
N78-3450	30	90	DFT-16QAM	M	Inner_Full	21.64	PC2	PASS

-3550								
N78-3450 -3550	30	90	DFT-16QAM	M	Edge_1RB_Left	21.77	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Edge_1RB_Right	21.64	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Outer_Full	21.59	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Inner_Full	21.64	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Edge_1RB_Left	21.57	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Edge_1RB_Right	21.58	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Outer_Full	21.57	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Inner_Full	21.56	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Edge_1RB_Left	21.42	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Edge_1RB_Right	21.46	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Outer_Full	21.58	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Inner_Full	21.65	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Edge_1RB_Left	21.39	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Edge_1RB_Right	21.39	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Outer_Full	21.57	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Inner_Full	21.60	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Edge_1RB_Left	21.24	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Edge_1RB_Right	21.18	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Outer_Full	21.60	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Inner_Full	22.10	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Edge_1RB_Left	21.39	PC2	PASS

N78-3450 -3550	30	100	DFT-QPSK	M	Edge_1RB_Right	21.40	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Outer_Full	21.59	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Inner_Full	21.62	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Edge_1RB_Left	21.24	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Edge_1RB_Right	21.17	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Outer_Full	21.59	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Inner_Full	21.63	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Edge_1RB_Left	21.40	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Edge_1RB_Right	21.39	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Outer_Full	21.57	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Inner_Full	21.63	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Edge_1RB_Left	21.27	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Edge_1RB_Right	21.21	PC2	PASS

Receiver ON

Band	SCS	Bandwidth	Modulation	Channel	RB Config	Power (dBm)	Power Class	Verdict
N78-3450 -3550	30	10	DFT-QPSK	L	Outer_Full	18.28	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Inner_Full	18.27	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Edge_1RB_Left	18.60	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Edge_1RB_Right	18.58	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Outer_Full	18.18	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Inner_Full	18.16	PC2	PASS

N78-3450 -3550	30	10	DFT-16QAM	L	Edge_1RB_Left	18.63	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Edge_1RB_Right	18.59	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Outer_Full	18.33	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Inner_Full	18.22	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Edge_1RB_Left	18.54	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Edge_1RB_Right	18.36	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Outer_Full	18.25	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Inner_Full	18.22	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Edge_1RB_Left	18.78	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Edge_1RB_Right	18.69	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Outer_Full	18.19	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Inner_Full	18.16	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Edge_1RB_Left	18.23	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Edge_1RB_Right	18.35	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Outer_Full	18.23	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Inner_Full	18.12	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Edge_1RB_Left	18.20	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Edge_1RB_Right	18.41	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Outer_Full	18.38	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Inner_Full	18.28	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Edge_1RB_Left	18.39	PC2	PASS
N78-3450	30	15	DFT-QPSK	L	Edge_1RB_Right	18.34	PC2	PASS

-3550								
N78-3450 -3550	30	15	DFT-16QAM	L	Outer_Full	18.40	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Inner_Full	18.43	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Edge_1RB_Left	18.20	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Edge_1RB_Right	18.19	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Outer_Full	18.33	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Inner_Full	18.28	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Edge_1RB_Left	18.25	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Edge_1RB_Right	18.19	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Outer_Full	18.35	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Inner_Full	18.25	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Edge_1RB_Left	18.51	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Edge_1RB_Right	18.45	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Outer_Full	18.20	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Inner_Full	18.09	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Edge_1RB_Left	18.21	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Edge_1RB_Right	18.38	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Outer_Full	18.17	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Inner_Full	18.26	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Edge_1RB_Left	17.89	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Edge_1RB_Right	18.05	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Outer_Full	18.30	PC2	PASS

N78-3450 -3550	30	20	DFT-QPSK	L	Inner_Full	18.34	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Edge_1RB_Left	18.50	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Edge_1RB_Right	18.46	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Outer_Full	18.37	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Inner_Full	18.28	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Edge_1RB_Left	18.45	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Edge_1RB_Right	18.46	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Outer_Full	18.42	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Inner_Full	18.28	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Edge_1RB_Left	18.52	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Edge_1RB_Right	18.43	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Outer_Full	18.27	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Inner_Full	18.28	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Edge_1RB_Left	18.90	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Edge_1RB_Right	18.80	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Outer_Full	18.19	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Inner_Full	18.07	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Edge_1RB_Left	18.31	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Edge_1RB_Right	18.40	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Outer_Full	18.04	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Inner_Full	18.08	PC2	PASS
N78-3450	30	20	DFT-16QAM	H	Edge_1RB_Left	18.33	PC2	PASS

-3550								
N78-3450 -3550	30	20	DFT-16QAM	H	Edge_1RB_Right	18.45	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Outer_Full	18.41	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Inner_Full	18.32	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Edge_1RB_Left	18.39	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Edge_1RB_Right	18.58	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Outer_Full	18.42	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Inner_Full	18.46	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Edge_1RB_Left	18.34	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Edge_1RB_Right	18.50	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Outer_Full	18.50	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Inner_Full	18.27	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Edge_1RB_Left	18.71	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Edge_1RB_Right	18.59	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Outer_Full	18.44	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Inner_Full	18.37	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Edge_1RB_Left	18.91	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Edge_1RB_Right	18.79	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Outer_Full	18.22	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Inner_Full	18.12	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Edge_1RB_Left	18.46	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Edge_1RB_Right	18.39	PC2	PASS

N78-3450 -3550	30	40	DFT-16QAM	H	Outer_Full	18.18	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Inner_Full	18.18	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Edge_1RB_Left	18.00	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Edge_1RB_Right	17.92	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Outer_Full	18.46	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Inner_Full	18.39	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Edge_1RB_Left	18.49	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Edge_1RB_Right	18.39	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Outer_Full	18.42	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Inner_Full	18.48	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Edge_1RB_Left	18.42	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Edge_1RB_Right	18.38	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Outer_Full	18.50	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Inner_Full	18.37	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Edge_1RB_Left	18.66	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Edge_1RB_Right	18.57	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Outer_Full	18.55	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Inner_Full	18.42	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Edge_1RB_Left	18.93	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Edge_1RB_Right	18.89	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Outer_Full	18.26	PC2	PASS
N78-3450	30	50	DFT-QPSK	H	Inner_Full	18.24	PC2	PASS

-3550								
N78-3450 -3550	30	50	DFT-QPSK	H	Edge_1RB_Left	18.46	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Edge_1RB_Right	18.50	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Outer_Full	18.25	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Inner_Full	18.25	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Edge_1RB_Left	18.34	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Edge_1RB_Right	18.38	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Outer_Full	18.42	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Inner_Full	18.48	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Edge_1RB_Left	18.37	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Edge_1RB_Right	18.34	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Outer_Full	18.41	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Inner_Full	18.56	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Edge_1RB_Left	18.23	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Edge_1RB_Right	18.17	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Outer_Full	18.41	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Inner_Full	18.31	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Edge_1RB_Left	18.34	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Edge_1RB_Right	18.28	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Outer_Full	18.43	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Inner_Full	18.40	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Edge_1RB_Left	18.49	PC2	PASS

N78-3450 -3550	30	60	DFT-16QAM	M	Edge_1RB_Right	18.45	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Outer_Full	18.31	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Inner_Full	18.29	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Edge_1RB_Left	18.47	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Edge_1RB_Right	18.37	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Outer_Full	18.27	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Inner_Full	18.36	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Edge_1RB_Left	18.19	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Edge_1RB_Right	18.05	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Outer_Full	18.53	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Inner_Full	18.52	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Edge_1RB_Left	18.57	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Edge_1RB_Right	18.56	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Outer_Full	18.47	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Inner_Full	18.59	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Edge_1RB_Left	18.48	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Edge_1RB_Right	18.53	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Outer_Full	18.50	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Inner_Full	18.46	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Edge_1RB_Left	18.44	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Edge_1RB_Right	18.25	PC2	PASS
N78-3450	30	70	DFT-16QAM	M	Outer_Full	18.50	PC2	PASS

-3550								
N78-3450 -3550	30	70	DFT-16QAM	M	Inner_Full	18.51	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Edge_1RB_Left	18.79	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Edge_1RB_Right	18.57	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Outer_Full	18.45	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Inner_Full	18.36	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Edge_1RB_Left	18.78	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Edge_1RB_Right	18.54	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Outer_Full	18.40	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Inner_Full	18.43	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Edge_1RB_Left	18.71	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Edge_1RB_Right	18.50	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Outer_Full	18.47	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Inner_Full	18.49	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Edge_1RB_Left	18.52	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Edge_1RB_Right	18.36	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Outer_Full	18.47	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Inner_Full	18.58	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Edge_1RB_Left	18.40	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Edge_1RB_Right	18.21	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Outer_Full	18.50	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Inner_Full	18.47	PC2	PASS

N78-3450 -3550	30	80	DFT-QPSK	M	Edge_1RB_Left	18.44	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Edge_1RB_Right	18.24	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Outer_Full	18.48	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Inner_Full	18.50	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Edge_1RB_Left	18.57	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Edge_1RB_Right	18.38	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Outer_Full	18.41	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Inner_Full	18.35	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Edge_1RB_Left	18.54	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Edge_1RB_Right	18.49	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Outer_Full	18.38	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Inner_Full	18.39	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Edge_1RB_Left	18.22	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Edge_1RB_Right	18.16	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Outer_Full	18.46	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Inner_Full	18.51	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Edge_1RB_Left	18.49	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Edge_1RB_Right	18.24	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Outer_Full	18.51	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Inner_Full	18.59	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Edge_1RB_Left	18.39	PC2	PASS
N78-3450	30	90	DFT-16QAM	L	Edge_1RB_Right	18.17	PC2	PASS

-3550								
N78-3450 -3550	30	90	DFT-QPSK	M	Outer_Full	18.57	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Inner_Full	18.50	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Edge_1RB_Left	18.41	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Edge_1RB_Right	18.26	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Outer_Full	18.53	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Inner_Full	18.59	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Edge_1RB_Left	18.80	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Edge_1RB_Right	18.64	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Outer_Full	18.49	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Inner_Full	18.51	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Edge_1RB_Left	18.54	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Edge_1RB_Right	18.54	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Outer_Full	18.48	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Inner_Full	18.50	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Edge_1RB_Left	18.44	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Edge_1RB_Right	18.44	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Outer_Full	18.51	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Inner_Full	18.50	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Edge_1RB_Left	18.32	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Edge_1RB_Right	18.30	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Outer_Full	18.49	PC2	PASS

N78-3450 -3550	30	100	DFT-16QAM	L	Inner_Full	18.52	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Edge_1RB_Left	18.19	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Edge_1RB_Right	18.16	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Outer_Full	18.53	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Inner_Full	18.54	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Edge_1RB_Left	18.33	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Edge_1RB_Right	18.28	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Outer_Full	18.48	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Inner_Full	18.52	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Edge_1RB_Left	18.23	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Edge_1RB_Right	18.17	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Outer_Full	18.95	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Inner_Full	18.50	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Edge_1RB_Left	18.36	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Edge_1RB_Right	18.27	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Outer_Full	18.51	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Inner_Full	18.54	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Edge_1RB_Left	18.23	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Edge_1RB_Right	18.19	PC2	PASS

Sensor ON

Band	SCS	Bandwidth	Modulation	Channel	RB Config	Power (dBm)	Power Class	Verdict
------	-----	-----------	------------	---------	-----------	-------------	-------------	---------

N78-3450 -3550	30	10	DFT-QPSK	L	Outer_Full	21.97	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Inner_Full	22.11	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Edge_1RB_Left	22.35	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	L	Edge_1RB_Right	22.32	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Outer_Full	21.98	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Inner_Full	21.86	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Edge_1RB_Left	22.35	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	L	Edge_1RB_Right	22.35	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Outer_Full	21.96	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Inner_Full	22.00	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Edge_1RB_Left	22.23	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	M	Edge_1RB_Right	22.08	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Outer_Full	22.07	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Inner_Full	21.96	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Edge_1RB_Left	22.46	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	M	Edge_1RB_Right	22.33	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Outer_Full	21.88	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Inner_Full	21.90	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Edge_1RB_Left	21.89	PC2	PASS
N78-3450 -3550	30	10	DFT-QPSK	H	Edge_1RB_Right	22.08	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Outer_Full	21.95	PC2	PASS
N78-3450	30	10	DFT-16QAM	H	Inner_Full	21.87	PC2	PASS

-3550								
N78-3450 -3550	30	10	DFT-16QAM	H	Edge_1RB_Left	21.82	PC2	PASS
N78-3450 -3550	30	10	DFT-16QAM	H	Edge_1RB_Right	21.98	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Outer_Full	22.03	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Inner_Full	22.07	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Edge_1RB_Left	22.07	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	L	Edge_1RB_Right	22.02	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Outer_Full	22.27	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Inner_Full	22.18	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Edge_1RB_Left	21.84	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	L	Edge_1RB_Right	21.86	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Outer_Full	22.08	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Inner_Full	22.06	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Edge_1RB_Left	21.94	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	M	Edge_1RB_Right	21.85	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Outer_Full	22.11	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Inner_Full	22.02	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Edge_1RB_Left	22.23	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	M	Edge_1RB_Right	22.19	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Outer_Full	21.95	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Inner_Full	21.88	PC2	PASS
N78-3450 -3550	30	15	DFT-QPSK	H	Edge_1RB_Left	21.90	PC2	PASS

N78-3450 -3550	30	15	DFT-QPSK	H	Edge_1RB_Right	22.10	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Outer_Full	21.95	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Inner_Full	21.88	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Edge_1RB_Left	21.58	PC2	PASS
N78-3450 -3550	30	15	DFT-16QAM	H	Edge_1RB_Right	21.88	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Outer_Full	22.02	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Inner_Full	22.06	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Edge_1RB_Left	22.16	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	L	Edge_1RB_Right	22.18	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Outer_Full	22.09	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Inner_Full	22.01	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Edge_1RB_Left	22.14	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	L	Edge_1RB_Right	22.11	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Outer_Full	22.08	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Inner_Full	22.04	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Edge_1RB_Left	22.21	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	M	Edge_1RB_Right	22.07	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Outer_Full	22.08	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Inner_Full	21.97	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Edge_1RB_Left	22.65	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	M	Edge_1RB_Right	22.51	PC2	PASS
N78-3450	30	20	DFT-QPSK	H	Outer_Full	21.91	PC2	PASS

-3550								
N78-3450 -3550	30	20	DFT-QPSK	H	Inner_Full	21.87	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Edge_1RB_Left	21.99	PC2	PASS
N78-3450 -3550	30	20	DFT-QPSK	H	Edge_1RB_Right	22.09	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Outer_Full	21.87	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Inner_Full	21.79	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Edge_1RB_Left	21.96	PC2	PASS
N78-3450 -3550	30	20	DFT-16QAM	H	Edge_1RB_Right	22.06	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Outer_Full	22.11	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Inner_Full	22.12	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Edge_1RB_Left	22.05	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	L	Edge_1RB_Right	22.25	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Outer_Full	22.16	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Inner_Full	22.13	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Edge_1RB_Left	22.03	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	L	Edge_1RB_Right	22.20	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Outer_Full	22.17	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Inner_Full	22.06	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Edge_1RB_Left	22.39	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	M	Edge_1RB_Right	22.28	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Outer_Full	22.22	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Inner_Full	22.09	PC2	PASS

N78-3450 -3550	30	40	DFT-16QAM	M	Edge_1RB_Left	22.61	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	M	Edge_1RB_Right	22.55	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Outer_Full	21.96	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Inner_Full	21.92	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Edge_1RB_Left	22.12	PC2	PASS
N78-3450 -3550	30	40	DFT-QPSK	H	Edge_1RB_Right	22.09	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Outer_Full	21.95	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Inner_Full	21.92	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Edge_1RB_Left	21.73	PC2	PASS
N78-3450 -3550	30	40	DFT-16QAM	H	Edge_1RB_Right	21.71	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Outer_Full	22.12	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Inner_Full	22.22	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Edge_1RB_Left	22.14	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	L	Edge_1RB_Right	22.05	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Outer_Full	22.20	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Inner_Full	22.14	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Edge_1RB_Left	22.10	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	L	Edge_1RB_Right	22.04	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Outer_Full	22.19	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Inner_Full	22.16	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	M	Edge_1RB_Left	22.36	PC2	PASS
N78-3450	30	50	DFT-QPSK	M	Edge_1RB_Right	22.22	PC2	PASS

-3550								
N78-3450 -3550	30	50	DFT-16QAM	M	Outer_Full	22.26	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Inner_Full	22.09	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Edge_1RB_Left	22.55	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	M	Edge_1RB_Right	22.48	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Outer_Full	21.95	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Inner_Full	22.04	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Edge_1RB_Left	22.10	PC2	PASS
N78-3450 -3550	30	50	DFT-QPSK	H	Edge_1RB_Right	22.15	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Outer_Full	21.99	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Inner_Full	21.95	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Edge_1RB_Left	21.89	PC2	PASS
N78-3450 -3550	30	50	DFT-16QAM	H	Edge_1RB_Right	22.01	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Outer_Full	22.09	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Inner_Full	22.20	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Edge_1RB_Left	22.03	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	L	Edge_1RB_Right	22.01	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Outer_Full	22.16	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Inner_Full	22.23	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Edge_1RB_Left	21.86	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	L	Edge_1RB_Right	21.86	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Outer_Full	22.14	PC2	PASS

N78-3450 -3550	30	60	DFT-QPSK	M	Inner_Full	22.11	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Edge_1RB_Left	22.00	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	M	Edge_1RB_Right	21.96	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Outer_Full	22.22	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Inner_Full	22.06	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Edge_1RB_Left	22.22	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	M	Edge_1RB_Right	22.16	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Outer_Full	22.01	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Inner_Full	22.09	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Edge_1RB_Left	22.15	PC2	PASS
N78-3450 -3550	30	60	DFT-QPSK	H	Edge_1RB_Right	22.05	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Outer_Full	22.06	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Inner_Full	22.04	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Edge_1RB_Left	21.89	PC2	PASS
N78-3450 -3550	30	60	DFT-16QAM	H	Edge_1RB_Right	21.80	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Outer_Full	22.21	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Inner_Full	22.27	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Edge_1RB_Left	22.22	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	L	Edge_1RB_Right	22.24	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Outer_Full	22.21	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	L	Inner_Full	22.28	PC2	PASS
N78-3450	30	70	DFT-16QAM	L	Edge_1RB_Left	22.19	PC2	PASS

-3550								
N78-3450 -3550	30	70	DFT-16QAM	L	Edge_1RB_Right	22.22	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Outer_Full	22.25	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Inner_Full	22.21	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Edge_1RB_Left	22.16	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	M	Edge_1RB_Right	21.94	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Outer_Full	22.30	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Inner_Full	22.19	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Edge_1RB_Left	22.45	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	M	Edge_1RB_Right	22.24	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Outer_Full	22.16	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Inner_Full	22.16	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Edge_1RB_Left	22.44	PC2	PASS
N78-3450 -3550	30	70	DFT-QPSK	H	Edge_1RB_Right	22.23	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Outer_Full	22.18	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Inner_Full	22.08	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Edge_1RB_Left	22.32	PC2	PASS
N78-3450 -3550	30	70	DFT-16QAM	H	Edge_1RB_Right	22.13	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Outer_Full	22.22	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Inner_Full	22.29	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Edge_1RB_Left	22.17	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	L	Edge_1RB_Right	22.09	PC2	PASS

N78-3450 -3550	30	80	DFT-16QAM	L	Outer_Full	22.32	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Inner_Full	22.27	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Edge_1RB_Left	22.04	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	L	Edge_1RB_Right	21.86	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Outer_Full	22.19	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Inner_Full	22.26	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Edge_1RB_Left	22.12	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	M	Edge_1RB_Right	21.93	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Outer_Full	22.29	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Inner_Full	22.20	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Edge_1RB_Left	22.31	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	M	Edge_1RB_Right	22.16	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Outer_Full	22.15	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Inner_Full	22.18	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Edge_1RB_Left	22.18	PC2	PASS
N78-3450 -3550	30	80	DFT-QPSK	H	Edge_1RB_Right	22.15	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Outer_Full	22.19	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Inner_Full	22.12	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Edge_1RB_Left	22.01	PC2	PASS
N78-3450 -3550	30	80	DFT-16QAM	H	Edge_1RB_Right	21.90	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Outer_Full	22.18	PC2	PASS
N78-3450	30	90	DFT-QPSK	L	Inner_Full	22.26	PC2	PASS

-3550								
N78-3450 -3550	30	90	DFT-QPSK	L	Edge_1RB_Left	22.14	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	L	Edge_1RB_Right	21.94	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Outer_Full	22.23	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Inner_Full	22.28	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Edge_1RB_Left	22.13	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	L	Edge_1RB_Right	21.92	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Outer_Full	22.19	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Inner_Full	22.29	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Edge_1RB_Left	22.11	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	M	Edge_1RB_Right	21.93	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Outer_Full	22.24	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Inner_Full	22.28	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Edge_1RB_Left	22.40	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	M	Edge_1RB_Right	22.24	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Outer_Full	22.21	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Inner_Full	22.25	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Edge_1RB_Left	22.19	PC2	PASS
N78-3450 -3550	30	90	DFT-QPSK	H	Edge_1RB_Right	22.21	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Outer_Full	22.31	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Inner_Full	22.18	PC2	PASS
N78-3450 -3550	30	90	DFT-16QAM	H	Edge_1RB_Left	22.01	PC2	PASS

N78-3450 -3550	30	90	DFT-16QAM	H	Edge_1RB_Right	22.02	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Outer_Full	22.20	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Inner_Full	22.26	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Edge_1RB_Left	21.97	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	L	Edge_1RB_Right	21.99	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Outer_Full	22.20	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Inner_Full	22.21	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Edge_1RB_Left	21.85	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	L	Edge_1RB_Right	21.81	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Outer_Full	22.16	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Inner_Full	22.26	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Edge_1RB_Left	21.99	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	M	Edge_1RB_Right	22.01	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Outer_Full	22.22	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Inner_Full	22.24	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Edge_1RB_Left	21.90	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	M	Edge_1RB_Right	21.82	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Outer_Full	22.16	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Inner_Full	22.67	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Edge_1RB_Left	22.00	PC2	PASS
N78-3450 -3550	30	100	DFT-QPSK	H	Edge_1RB_Right	22.01	PC2	PASS
N78-3450	30	100	DFT-16QAM	H	Outer_Full	22.28	PC2	PASS

-3550								
N78-3450 -3550	30	100	DFT-16QAM	H	Inner_Full	22.23	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Edge_1RB_Left	21.87	PC2	PASS
N78-3450 -3550	30	100	DFT-16QAM	H	Edge_1RB_Right	21.83	PC2	PASS

Appendix B: Peak-to-Average Ratio for SA

Peak-to-Average Ratio(PAPR)

Test Result

Band	SCS	Bandwidth	Modulation	Channel	RB Config	DutyCycle	Factor	Result	Limit	Verdict
N78-3450-3550	30	10	DFT-QPSK	L	Outer_Full	100%	0.00	7.41	≤13	PASS
N78-3450-3550	30	10	DFT-16QAM	L	Outer_Full	100%	0.00	7.79	≤13	PASS
N78-3450-3550	30	10	DFT-QPSK	M	Outer_Full	100%	0.00	7.62	≤13	PASS
N78-3450-3550	30	10	DFT-16QAM	M	Outer_Full	100%	0.00	7.82	≤13	PASS
N78-3450-3550	30	10	DFT-QPSK	H	Outer_Full	100%	0.00	7.68	≤13	PASS
N78-3450-3550	30	10	DFT-16QAM	H	Outer_Full	100%	0.00	7.66	≤13	PASS
N78-3450-3550	30	15	DFT-QPSK	L	Outer_Full	100%	0.00	7.87	≤13	PASS
N78-3450-3550	30	15	DFT-16QAM	L	Outer_Full	100%	0.00	8.55	≤13	PASS
N78-3450-3550	30	15	DFT-QPSK	M	Outer_Full	100%	0.00	8.06	≤13	PASS
N78-3450-3550	30	15	DFT-16QAM	M	Outer_Full	100%	0.00	7.85	≤13	PASS
N78-3450-3550	30	15	DFT-QPSK	H	Outer_Full	100%	0.00	7.53	≤13	PASS
N78-3450-3550	30	15	DFT-16QAM	H	Outer_Full	100%	0.00	8.60	≤13	PASS
N78-3450-3550	30	20	DFT-QPSK	L	Outer_Full	100%	0.00	8.41	≤13	PASS
N78-3450-3550	30	20	DFT-16QAM	L	Outer_Full	100%	0.00	8.22	≤13	PASS
N78-3450-3550	30	20	DFT-QPSK	M	Outer_Full	100%	0.00	8.41	≤13	PASS
N78-3450-3550	30	20	DFT-16QAM	M	Outer_Full	100%	0.00	8.14	≤13	PASS
N78-3450-3550	30	20	DFT-QPSK	H	Outer_Full	100%	0.00	8.11	≤13	PASS
N78-3450-3550	30	20	DFT-16QAM	H	Outer_Full	100%	0.00	8.29	≤13	PASS
N78-3450-3550	30	40	DFT-QPSK	L	Outer_Full	100%	0.00	8.08	≤13	PASS
N78-3450-3550	30	40	DFT-16QAM	L	Outer_Full	100%	0.00	8.15	≤13	PASS
N78-3450-3550	30	40	DFT-QPSK	M	Outer_Full	100%	0.00	8.17	≤13	PASS
N78-3450-3550	30	40	DFT-16QAM	M	Outer_Full	100%	0.00	9.03	≤13	PASS
N78-3450-3550	30	40	DFT-QPSK	H	Outer_Full	100%	0.00	8.56	≤13	PASS
N78-3450-3550	30	40	DFT-16QAM	H	Outer_Full	100%	0.00	8.65	≤13	PASS
N78-3450-3550	30	50	DFT-QPSK	L	Outer_Full	100%	0.00	8.47	≤13	PASS
N78-3450-3550	30	50	DFT-16QAM	L	Outer_Full	100%	0.00	8.91	≤13	PASS
N78-3450-3550	30	50	DFT-QPSK	M	Outer_Full	100%	0.00	8.82	≤13	PASS
N78-3450-3550	30	50	DFT-16QAM	M	Outer_Full	100%	0.00	9.36	≤13	PASS
N78-3450-3550	30	50	DFT-QPSK	H	Outer_Full	19.6%	7.08	1.61	≤13	PASS
N78-3450-3550	30	50	DFT-16QAM	H	Outer_Full	19.6%	7.08	1.41	≤13	PASS
N78-3450-3550	30	60	DFT-QPSK	L	Outer_Full	19.6%	7.08	1.28	≤13	PASS
N78-3450-3550	30	60	DFT-16QAM	L	Outer_Full	19.6%	7.08	1.70	≤13	PASS
N78-3450-3550	30	60	DFT-QPSK	M	Outer_Full	19.6%	7.08	1.61	≤13	PASS
N78-3450-3550	30	60	DFT-16QAM	M	Outer_Full	19.6%	7.08	1.85	≤13	PASS
N78-3450-3550	30	60	DFT-QPSK	H	Outer_Full	19.6%	7.08	1.39	≤13	PASS

N78-3450-3550	30	60	DFT-16QAM	H	Outer_Full	19.6%	7.08	1.61	≤13	PASS
N78-3450-3550	30	70	DFT-QPSK	L	Outer_Full	19.6%	7.08	1.25	≤13	PASS
N78-3450-3550	30	70	DFT-16QAM	L	Outer_Full	19.6%	7.08	1.45	≤13	PASS
N78-3450-3550	30	70	DFT-QPSK	M	Outer_Full	19.6%	7.08	1.35	≤13	PASS
N78-3450-3550	30	70	DFT-16QAM	M	Outer_Full	19.6%	7.08	1.75	≤13	PASS
N78-3450-3550	30	70	DFT-QPSK	H	Outer_Full	19.6%	7.08	1.24	≤13	PASS
N78-3450-3550	30	70	DFT-16QAM	H	Outer_Full	19.6%	7.08	1.62	≤13	PASS
N78-3450-3550	30	80	DFT-QPSK	L	Outer_Full	19.6%	7.08	1.91	≤13	PASS
N78-3450-3550	30	80	DFT-16QAM	L	Outer_Full	19.6%	7.08	1.52	≤13	PASS
N78-3450-3550	30	80	DFT-QPSK	M	Outer_Full	19.6%	7.08	1.53	≤13	PASS
N78-3450-3550	30	80	DFT-16QAM	M	Outer_Full	19.6%	7.08	1.69	≤13	PASS
N78-3450-3550	30	80	DFT-QPSK	H	Outer_Full	19.6%	7.08	1.71	≤13	PASS
N78-3450-3550	30	80	DFT-16QAM	H	Outer_Full	19.6%	7.08	1.21	≤13	PASS
N78-3450-3550	30	90	DFT-QPSK	L	Outer_Full	19.6%	7.08	1.62	≤13	PASS
N78-3450-3550	30	90	DFT-16QAM	L	Outer_Full	19.6%	7.08	1.26	≤13	PASS
N78-3450-3550	30	90	DFT-QPSK	M	Outer_Full	19.6%	7.08	1.23	≤13	PASS
N78-3450-3550	30	90	DFT-16QAM	M	Outer_Full	19.6%	7.08	2.09	≤13	PASS
N78-3450-3550	30	90	DFT-QPSK	H	Outer_Full	19.6%	7.08	1.66	≤13	PASS
N78-3450-3550	30	90	DFT-16QAM	H	Outer_Full	19.6%	7.08	1.45	≤13	PASS
N78-3450-3550	30	100	DFT-QPSK	L	Outer_Full	19.6%	7.08	1.22	≤13	PASS
N78-3450-3550	30	100	DFT-16QAM	L	Outer_Full	19.6%	7.08	1.68	≤13	PASS
N78-3450-3550	30	100	DFT-QPSK	M	Outer_Full	19.6%	7.08	1.42	≤13	PASS
N78-3450-3550	30	100	DFT-16QAM	M	Outer_Full	19.6%	7.08	1.87	≤13	PASS
N78-3450-3550	30	100	DFT-QPSK	H	Outer_Full	19.6%	7.08	1.33	≤13	PASS
N78-3450-3550	30	100	DFT-16QAM	H	Outer_Full	19.6%	7.08	1.28	≤13	PASS

Test Graphs









