


Different Announcement


We declare that,

Product Multimedia Player Assembly, series model: TR6602/40 is the same as TR3392/40 in DAB function, RAM, RF module, storage capacity, Bluetooth chip, GNSS chip, FM and AM chip and etc. Schematic, circuit design, layout, Hardware version, Software version are different as below detail-

1. The appearance designs of the sample are different as below picture.
2. The functions are different. TR6602/40 has the Ethernet function. The TR3392/40 does not.
3. LVDS chips are different. The TR6602/40 uses DS90UB949, and the TR3392/40 uses MAX96751. The chip is replaced with the same type of chip as pin to pin.





TR6602/40



TR3392/40

4、 The location of the updated candidate chip (U400) is shown in the following figure:



德赛西威

创·领·智·行 For Internal Only

5. Hardware version of TR3392/40 is HW001, Software version:S018A02XPS11001.
And Hardware version of TR6602/40 is HW000, Software version:S018A04XST10001.

6. Application requirement: adding new model TR6602/40 and this is request a Class II
permissive change for FCC ID: 2AEQTNV101140, granted on 2022-08-04.

Responsible person: Deng Ailing 

Huizhou Desay SV Automotive Co., Ltd





卷之三