

Jan.09, 2024

Office of Engineering Technology
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046
USA

Subject: Explanation of differences between product types

FCC ID : 2AFIOWJRC5151

Model Number: RC5151, RC5101, RC5102, RC5103, RC5104, RC5105, RC5106, RC5107, RC5108, RC5109, RC5110, RC5111, RC5112, RC5113, RC5114, RC5115, RC5116, RC5117, RC5118, RC5119, RC5120, RC5121, RC5122, RC5123, RC5124, RC5125, RC5126, RC5127, RC5128, RC5129, RC5130, RC5131, RC5132, RC5133, RC5134, RC5135, RC5136, RC5137, RC5138, RC5139, RC5140, RC5141, RC5142, RC5143, RC5144, RC5145, RC5146, RC5147, RC5148, RC5149, RC5150, RC5152, RC5153, RC5154, RC5155, RC5156, RC5157, RC5158, RC5159, RC5160, RC5161, RC5162, RC5163, RC5164, RC5165, RC5166, RC5167, RC5168, RC5169, RC5170, RC5171, RC5172, RC5173, RC5174, RC5175, RC5176, RC5177, RC5178, RC5179, RC5180, ODY-03LZ

To Whom It May Concern:

We, The HUAJIA TECHNOLOGY INDUSTRY CO.,LTD. hereby declare that the models are identical except the model names and the color of appearance.

Except for the different above, no other modification is performed.

Sincerely,

Signature:

Jimmy Lin

Contact person: Jimmy Lin