



**LISTED**  
E365015  
Temp. Ind. & Reg. Equip.



SunStat ConnectPlus  
GFCI CLASS A Jul 2015  
1139-01 Lot 12345  
Designed and assembled  
in Canada

**CAUTION:**  
High Voltage - disconnect power supply before servicing. To reduce the risk of electrical shock - do not connect to a circuit operating at more than 150 V to ground.

**ATTENTION**  
Haute tension - débranchez la source d'alimentation avant un travail de maintenance. Pour réduire les risques d'électrocution choc - ne pas raccorder à un circuit fonctionnant à plus de 150 V à la terre.

Meets CAN ICES-3 (B)/NMB-3(B), FCC Part 15B;  
FCC ID: 2AFJT-11390A, IC: 20938-11390A  
Contains: FCC ID: 2AC7Z-ESP32WROOM32U  
Contains: IC: 21098-ESPWROOM32U

Use copper conductors only

|           |
|-----------|
| AWAY      |
| COM (A)   |
| RELAY (B) |
| SENSOR    |
| SENSOR    |
| W2        |
| W2        |

Notes:

Caution/Attention must be at least 1/8" high. Remaining warning text must be at least 1/16" high.

| Revision Table |                                             |            |             |          |
|----------------|---------------------------------------------|------------|-------------|----------|
| Rev #          | Description                                 | Date       | Revision By | Approved |
| 1              | Initial Release                             | 03/30/2020 | GB          |          |
| 2              | Removed Rear Label Artwork                  | 11/12/2020 | BK          |          |
| 3              | Changed product name to ConnectPlus         | 03/25/2021 | BK          |          |
| 4              | Adjusted Label to fit FCC Text, and outline | 04/23/2021 | GB          |          |
| 5              | Added final FCC and IC IDs                  | 06/17/2021 | GB          |          |
| 6              | Fixed ESP IDs, was D change to U            | 06/17/2021 | GB          |          |
| 7              | Added "Use copper conductors only"          | 10/19/2021 | GB          |          |

tekmar Control Systems Ltd.

Part N°: TBD

Part Rev:7

Drawing Version: 7

113901 SunStat Connect Labels

Drawn by: GB

Scale: 1x

Date: October 19, 2021

The information and drawings contained herein are the sole property of tekmar Control Systems Ltd. and shall not be disclosed to 3rd parties without the express written consent of tekmar.



**LISTED**  
E365015  
Temp. Ind. & Reg. Equip.

SunStat ConnectPlus

GFCI CLASS A    Jul 2015  
1139-02    Lot 12345  
Designed and assembled in Canada

**CAUTION:**  
High Voltage - disconnect power supply before servicing. To reduce the risk of electrical shock - do not connect to a circuit operating at more than 150 V to ground.

**ATTENTION**  
Haute tension - débranchez la source d'alimentation avant un travail de maintenance. Pour réduire les risques d'électrocution choc - ne pas raccorder à un circuit fonctionnant à plus de 150 V à la terre.

Meets CAN ICES-3 (B)/NMB-3(B), FCC Part 15B;  
FCC ID: 2AFJT-11390A, IC: 20938-11390A  
Contains: FCC ID: 2AC7Z-ESP32WROOM32U  
Contains: IC: 21098-ESPWROOM32U

Use copper conductors only

|           |
|-----------|
| AWAY      |
| COM (A)   |
| RELAY (B) |
| SENSOR    |
| SENSOR    |
| W2        |
| W2        |

Notes:

Caution/Attention must be at least 1/8" high. Remaining warning text must be at least 1/16" high.

| Revision Table |                 |            |             |          |
|----------------|-----------------|------------|-------------|----------|
| Rev #          | Description     | Date       | Revision By | Approved |
| 1              | Initial Release | 09/22/2020 | GB          |          |

tekmar Control Systems Ltd.

|              |             |                    |
|--------------|-------------|--------------------|
| Part N°: TBD | Part Rev: 1 | Drawing Version: 1 |
|--------------|-------------|--------------------|

113902 SunStat Connect Labels

|              |           |                          |
|--------------|-----------|--------------------------|
| Drawn by: GB | Scale: 1x | Date: September 23, 2021 |
|--------------|-----------|--------------------------|

The information and drawings contained herein are the sole property of tekmar Control Systems Ltd. and shall not be disclosed to 3rd parties without the express written consent of tekmar.



**LISTED**  
E365015  
Temp. Ind. & Reg. Equip.

**warmyourfloor.**

SunStat ConnectPlus  
GFCI CLASS A Jul 2015  
1139-03 Lot 12345  
Designed and assembled  
in Canada Use copper  
conductors only

**CAUTION:**  
High Voltage - disconnect power supply before servicing. To reduce the risk of electrical shock - do not connect to a circuit operating at more than 150 V to ground.

**ATTENTION**  
Haute tension - débranchez la source d'alimentation avant un travail de maintenance. Pour réduire les risques d'électrocution choc - ne pas raccorder à un circuit fonctionnant à plus de 150 V à la terre.

Meets CAN ICES-3 (B)/NMB-3(B), FCC Part 15B;  
FCC ID: 2AFJT-11390A, IC: 20938-11390A  
Contains: FCC ID: 2AC7Z-ESP32WROOM32U  
Contains: IC: 21098-ESPWROOM32U

AWAY

COM (A)

RELAY (B)

SENSOR

SENSOR

W2

W2

Notes:

Caution/Attention must be at least 1/8" high. Remaining warning text must be at least 1/16" high.

| Revision Table |                 |            |             |          |
|----------------|-----------------|------------|-------------|----------|
| Rev #          | Description     | Date       | Revision By | Approved |
| 1              | Initial Release | 09/22/2020 | GB          |          |

| tekmar Control Systems Ltd.                                                                                                                                                                 |             |                          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------------|
| Part N°: TBD                                                                                                                                                                                | Part Rev: 1 | Drawing Version: 1       |
| 113903 SunStat Connect Labels                                                                                                                                                               |             |                          |
| Drawn by: GB                                                                                                                                                                                | Scale: 1x   | Date: September 23, 2021 |
| The information and drawings contained herein are the sole property of tekmar Control Systems Ltd. and shall not be disclosed to 3rd parties without the express written consent of tekmar. |             |                          |



**LISTED**  
E365015  
Temp. Ind. & Reg. Equip.

**comfortone™**  
SunStat ConnectPlus  
GFCI CLASS A Jul 2015  
1139-04 Lot 12345  
Designed and assembled  
in Canada Use copper  
conductors only

**CAUTION:**  
High Voltage - disconnect power supply before servicing. To reduce the risk of electrical shock - do not connect to a circuit operating at more than 150 V to ground.

**ATTENTION**  
Haute tension - débranchez la source d'alimentation avant un travail de maintenance. Pour réduire les risques d'électrocution choc - ne pas raccorder à un circuit fonctionnant à plus de 150 V à la terre.

Meets CAN ICES-3 (B)/NMB-3(B), FCC Part 15B;  
FCC ID: 2AFJT-11390A, IC: 20938-11390A  
Contains: FCC ID: 2AC7Z-ESP32WROOM32U  
Contains: IC: 21098-ESPWROOM32U

AWAY

COM (A)

RELAY (B)

SENSOR

SENSOR

W2

W2

Notes:  
Caution/Attention must be at least 1/8" high. Remaining warning text must be at least 1/16" high.

| Revision Table |                 |            |             |          |
|----------------|-----------------|------------|-------------|----------|
| Rev #          | Description     | Date       | Revision By | Approved |
| 1              | Initial Release | 09/22/2020 | GB          |          |

|                                                                                                                                                                                             |             |                          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------------|
| tekmar Control Systems Ltd.                                                                                                                                                                 |             |                          |
| Part N°: TBD                                                                                                                                                                                | Part Rev: 1 | Drawing Version: 1       |
| 113904 SunStat Connect Labels                                                                                                                                                               |             |                          |
| Drawn by: GB                                                                                                                                                                                | Scale: 1x   | Date: September 23, 2021 |
| The information and drawings contained herein are the sole property of tekmar Control Systems Ltd. and shall not be disclosed to 3rd parties without the express written consent of tekmar. |             |                          |