

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules and
Multiple Listing of Certification service per clause 11.5 of RSP-100

Reference: FCC ID: 2AGGZMTDCBRF2511 and IC: 21769-MTDCBRF2511

Statement from applicant

On the behalf of Rolleace Acmeda Inc I am writing to apply for certification of the following product from our company:

Grantee name: Rolleace Acmeda Inc

Model / HVIN & PMN name: MTDCBRF25-1.1

FCC ID: 2AGGZMTDCBRF2511

IC: 21769-MTDCBRF2511

The above product, for which we are applying for certification, is identical to the following product:

Grantee name: NINGBO DOOYA MECHANIC & ELECTRONIC TECHNOLOGY CO., LTD.

Granted date of FCC and IC: 06/28/2016 and 10/19/2016

Model / HVIN & PMN name: DM25LE/S-1.1/40


Original FCC ID: VYYDM251140

Original IC: 21396-DM251140

in design, circuitry and construction except for trade name, model number and logo. The documents on file with FCC/ISED from the original certification remain unchanged and continue to be valid, except for user manual and label location.

As a result, the original test results of above FCC ID and IC granted product continue to be representative of and applicable to the product from our company for certification.

Date: Jan 10, 2019

By: 
(Signature¹)


Jere Gianola

Title: Program Manager - Motorization

On behalf of: Rolleace Acmeda Inc
(Company Name)

Telephone: +1 (203) 964-1573