



802.11n20_5180MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:07:20

802.11n20_5200MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:04:23

802.11n20_5240MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:05:43

802.11n20_5180MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:09:39

802.11n20_5200MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:11:02

802.11n20_5240MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:12:16

802.11n40_5190MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:16:33

802.11n40_5230MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:17:42

802.11n40_5190MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:21:09

802.11n40_5230MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:20:00

802.11ac80_5210MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:25:19

802.11ac80_5210MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:22:53

802.11ax20_5180MHz_RU_Full_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:32:47

802.11ax20_5200MHz_RU_Full_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:29:14

802.11ax20_5240MHz_RU_Full_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:30:51

802.11ax20_5180MHz_RU_Full_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:34:40

802.11ax20_5200MHz_RU_Full_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:36:18

802.11ax20_5240MHz_RU_Full_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:37:55

802.11ax40_5190MHz_RU_Full_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:52:44

802.11ax40_5230MHz_RU_Full_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:51:40

802.11ax40_5190MHz_RU_Full_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:49:02

802.11ax40_5230MHz_RU_Full_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:50:11

802.11ax80_5210MHz_RU_Full_Chain 0



ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:56:21


802.11ax80_5210MHz_RU_Full_Chain 1



ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:57:51


5725-5850MHz

802.11a_5745MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:07:59

802.11a_5785MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:05:06

802.11a_5825MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:06:34

802.11a_5745MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:09:03

802.11a_5785MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:11:17

802.11a_5825MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:12:34

802.11n20_5745MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:18:28

802.11n20_5785MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:19:47

802.11n20_5825MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:18:59

802.11n20_5745MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:20:21

802.11n20_5785MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:21:51

802.11n20_5825MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:24:15

802.11n40_5755MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:31:03

802.11n40_5795MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:32:11

802.11n40_5755MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:28:37

802.11n40_5795MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:29:25

802.11ac80_5775MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:36:12

802.11ac80_5775MHz_Chain 1




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 23:37:53


802.11ax20_5745MHz_RU_Full_Chain 0




802.11ax20_5785MHz_RU_Full_Chain 0




802.11ax20_5825MHz_RU_Full_Chain 0




802.11ax20_5745MHz_RU_Full_Chain 1




802.11ax20_5785MHz_RU_Full_Chain 1




802.11ax20_5825MHz_RU_Full_Chain 1




802.11ax40_5755MHz_RU_Full_Chain 0




802.11ax40_5795MHz_RU_Full_Chain 0




802.11ax40_5755MHz_RU_Full_Chain 1




802.11ax40_5795MHz_RU_Full_Chain 1



802.11ax80_5775MHz_RU_Full_Chain 0



802.11ax80_5775MHz_RU_Full_Chain 1



5.7 Duty Cycle

Test Information:

Serial No.:	2WN8-2	Test Date:	2025/01/16~2025/02/27
Test Site:	RF	Test Mode:	Transmitting
Tester:	Karl Liang	Test Result:	N/A

Environmental Conditions:

Temperature: (°C):	21.2~22.4	Relative Humidity: (%)	27~55	ATM Pressure: (kPa)	101.4~102.0
-----------------------	-----------	------------------------------	-------	------------------------	-------------

Test Equipment List and Details:

Manufacturer	Description	Model	Serial Number	Calibration Date	Calibration Due Date
Eastsheep	Coaxial Attenuator	5W-N-JK-6G-10dB	F-08-EM503	2024/06/07	2025/06/06
R&S	Spectrum Analyzer	FSV40	101589	2024/09/05	2025/09/04


* Statement of Traceability: Bay Area Compliance Laboratories Corp. (Dongguan) attests that all calibrations have been performed, traceable to National Primary Standards and International System of Units (SI).

Test Data:

Mode	Antenna	Test Frequency (MHz)	Ton (ms)	Ton+Toff (ms)	Duty Cycle (%)	Duty Cycle Factor (dB)	1/Ton (Hz)	VBW Setting (kHz)
802.11a	Chain 0	5200	1.394	1.494	93.31	0.30	717	1
802.11n20	Chain 0	5200	0.676	0.775	87.23	0.59	1479	2
802.11n40	Chain 0	5190	0.647	0.748	86.50	0.63	1546	2
802.11ac80	Chain 0	5210	2.238	2.260	99.03	/	/	0.010
802.11ax20_RU_Full	Chain 0	5200	1.486	1.517	97.96	0.09	673	1
802.11ax40_RU_Full	Chain 0	5190	0.771	0.801	96.25	0.17	1297	2
802.11ax80_RU_Full	Chain 0	5210	0.400	0.431	92.81	0.32	2500	3


Duty Cycle = Ton/(Ton+Toff)*100%

802.11a_5200MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 27.FEB.2025 15:16:03

802.11n20_5200MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 27.FEB.2025 15:17:31

802.11n40_5190MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 27.FEB.2025 15:18:45

802.11ac80_5210MHz_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:21:52

802.11ax20_5200MHz_RU_Full_Chain 0




ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:17:37

802.11ax40_5190MHz_RU_Full_Chain 0



ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16.JAN.2025 22:46:53

802.11ax80_5210MHz_RU_Full_Chain 0



ProjectNo.:2402A23350E-RF Tester:Karl Liang
Date: 16-JAN-2025 22:55:15

EXHIBIT A - EUT PHOTOGRAPHS

Please refer to the attachment 2402A23350E-RF-EXP EUT EXTERNAL PHOTOGRAPHS and 2402A23350E-RF-INP EUT INTERNAL PHOTOGRAPHS.

EXHIBIT B - TEST SETUP PHOTOGRAPHS

Please refer to the attachment 2402A23350E-RF-00B-TSP TEST SETUP PHOTOGRAPHS.

******* END OF REPORT *******