



LTE Band 38 , Normal
 1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
 Date: 7.MAR.2025 10:41:24

5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
 Date: 7.MAR.2025 10:41:45

5MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
 Date: 7.MAR.2025 10:42:07

10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
 Date: 7.MAR.2025 10:44:38

10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
 Date: 7.MAR.2025 10:45:00

10MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
 Date: 7.MAR.2025 10:45:22


15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




15MHz_High_QPSK_1@0(30MHz~27.2GHz)




20MHz_Low_QPSK_1@0(30MHz~27.2GHz)



20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




20MHz_High_QPSK_1@0(30MHz~27.2GHz)




LTE B41_2 , Normal
1RB was the worst case

2_5MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:51:18

2_5MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:51:40

2_5MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:52:02

2_10MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:53:29

2_10MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:53:50

2_10MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:54:11

2_15MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:55:15

2_15MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:55:37

2_15MHz_High_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:55:59

2_20MHz_Low_QPSK_1@0(30MHz~27.55GHz)




ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:57:23

2_20MHz_Middle_QPSK_1@0(30MHz~27.55GHz)



ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:57:45

2_20MHz_High_QPSK_1@0(30MHz~27.55GHz)



ProjectNo.:2502Q36948E-RF Tester:Karl Liang
Date: 7.MAR.2025 10:58:07

**** END ****