




Band 2_1.4 MHz_Middle_QPSK_RB6#0




Band 2_3 MHz_Middle_QPSK_RB15#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 18:29:10

Band 2_3 MHz_Middle_16QAM_RB15#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 18:29:27




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 18:48:46




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 18:49:00




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 18:55:48



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 18:56:07




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 18:59:07




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 18:59:25

Band 2_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:02:33

Band 2_20 MHz_Middle_16QAM_RB100#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:02:52


Band 4_1.4 MHz_Middle_QPSK_RB6#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:04:18

Band 4_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:04:32




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:07:13



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:07:27




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:14:57



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:15:13


Band 4_15 MHz_Middle_QPSK_RB75#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 4.JUL.2024 19:18:00


Band 4_15 MHz_Middle_16QAM_RB75#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:18:21

Band 4_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:20:39

Band 4_20 MHz_Middle_16QAM_RB100#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:20:58

Band 12_1.4 MHz_Middle_QPSK_RB6#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:22:49


Band 12_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:23:03




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:28:53




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:29:07




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:31:29



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:31:47





ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:34:04





ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:34:23


ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:34:44

ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:35:00






Band 7_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:41:02

Band 7_20 MHz_Middle_16QAM_RB100#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:41:19


Band 13_5 MHz_Middle_QPSK_RB25#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 23.JUL.2024 00:43:13


Band 13_5 MHz_Middle_16QAM_RB25#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 23.JUL.2024 00:43:33

Band 13_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:46:00

Band 13_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:46:17

Band 38_5 MHz_Middle_QPSK_RB25#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:47:35


Band 38_5 MHz_Middle_16QAM_RB25#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:47:52




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:50:03




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:50:26




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:52:47




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:53:16




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:55:41




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 00:56:00




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 01:02:22





ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 01:02:42




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 01:04:58




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 01:05:21





ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 01:10:25



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 23.JUL.2024 01:10:45