



Please refer to following plots:


For Band Edge 1RB:




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:07:20



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:07:50




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:06:27



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:05:58


Band 2_3 MHz_High_16QAM_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:12:30


Band 2_3 MHz_High_QPSK_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:12:04


Band 2_3 MHz_Low_16QAM_RB1#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 9.JUL.2024 20:13:14

Band 2_3 MHz_Low_QPSK_RB1#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:13:35




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:16:12



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:16:34


Band 2_5 MHz_Low_16QAM_RB1#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:15:16


Band 2_5 MHz_Low_QPSK_RB1#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:14:59


Band 2_10 MHz_High_16QAM_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 9.JUL.2024 20:18:27

Band 2_10 MHz_High_QPSK_RB1#Max




ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 9.JUL.2024 20:18:02




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:19:39




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:20:07



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:26:03




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:27:13



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 9.JUL.2024 20:25:19



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:24:47


Band 2_20 MHz_High_16QAM_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:29:15


Band 2_20 MHz_High_QPSK_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:28:56


Band 2_20 MHz_Low_16QAM_RB1#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:30:05

Band 2_20 MHz_Low_QPSK_RB1#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 9.JUL.2024 20:30:25




Date: 9.JUL.2024 21:07:37



Date: 9.JUL.2024 21:08:09




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:11:43



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:11:16


Band 4_3MHz_High_16QAM_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 21:14:19


Band 4_3MHz_High_QPSK_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 21:13:58


Band 4_3MHz_Low_16QAM_RB1#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 9.JUL.2024 21:12:40

Band 4_3MHz_Low_QPSK_RB1#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 21:13:02




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:15:53



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:15:18


Band 4_5MHz_Low_16QAM_RB1#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 9.JUL.2024 21:16:34

Band 4_5MHz_Low_QPSK_RB1#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 9.JUL.2024 21:16:58




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:19:39




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:20:06




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:18:10




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:17:43




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:21:33




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:21:12




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:25:40




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:26:04




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:28:04




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:28:34




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:27:20




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:26:58




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:37:03




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:37:23




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:35:10




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:36:04




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:40:21




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:40:03




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:02:23



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 21:02:43




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:55:44



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 9.JUL.2024 20:56:09


Band 12_10 MHz_High_16QAM_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:57:55


Band 12_10 MHz_High_QPSK_RB1#Max



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:58:15


Band 12_10 MHz_Low_16QAM_RB1#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 20:59:37


Band 12_10 MHz_Low_QPSK_RB1#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 9.JUL.2024 21:00:08


For Band Edge full RB:




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 20:04:47



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:35:51




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:35:58



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:36:05


Band 2_3 MHz_Low_QPSK_RB15#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:36:42

Band 2_3 MHz_Low_16QAM_RB15#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:36:47




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:36:55




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:37:01




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:37:38



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:37:44




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:37:51



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:37:58


Band 2_10 MHz_Low_QPSK_RB50#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:38:36

Band 2_10 MHz_Low_16QAM_RB50#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai



Date: 4.JUL.2024 19:38:43




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:38:50




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:38:58





ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:40:28




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:40:34




Date: 4.JUL.2024 19:40:41





Date: 4.JUL.2024 19:40:46




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:40:56



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:41:03




Band 4_3 MHz_Low_QPSK_RB15#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:41:53

Band 4_3 MHz_Low_16QAM_RB15#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 4.JUL.2024 19:41:59



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:42:06



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 4.JUL.2024 19:42:11


Band 4_5 MHz_Low_QPSK_RB25#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:42:49

Band 4_5 MHz_Low_16QAM_RB25#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 4.JUL.2024 19:42:56



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:43:03



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:43:09




Date: 4.JUL.2024 19:43:47



Date: 4.JUL.2024 19:43:55


Band 4_10 MHz_High_QPSK_RB50#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:44:02

Band 4_10 MHz_High_16QAM_RB50#0




ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:44:08




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:45:08




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:45:14




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:46:03




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:46:09




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:46:15




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:46:21




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:46:58



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:47:04




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:47:11



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:47:16


Band 12_3 MHz_Low_QPSK_RB15#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 4.JUL.2024 19:47:54


Band 12_3 MHz_Low_16QAM_RB15#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 4.JUL.2024 19:48:01


Band 12_3 MHz_High_QPSK_RB15#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai



Date: 4.JUL.2024 19:48:07


Band 12_3 MHz_High_16QAM_RB15#0



ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:48:13






ProjectNo.:2401T35202E-RF Tester:Allen Bai

Date: 4.JUL.2024 19:49:13




ProjectNo.:2401T35202E-RF Tester:Allen Bai


Date: 4.JUL.2024 19:49:18




ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:49:57



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:50:04



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:50:11



ProjectNo.:2401T35202E-RF Tester:Allen Bai
Date: 4.JUL.2024 19:50:17