




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 146 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 147 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 148 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 149 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 150 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 151 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 152 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 153 of 1085







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 154 of 1085

802.11n(HT20)_LCH_5180MHz_Ant1_NTNV




802.11n(HT20)_LCH_5180MHz_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 155 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 156 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 157 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 158 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 159 of 1085







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 160 of 1085

802.11n(HT20)_LCH_5500MHz_Ant1_NTNV




802.11n(HT20)_LCH_5500MHz_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 161 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 162 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 163 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 164 of 1085







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 165 of 1085

802.11n(HT40)_LCH_5270MHz_Ant1_NTNV




802.11n(HT40)_LCH_5270MHz_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 166 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 167 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 168 of 1085







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 169 of 1085

802.11n(HT40)_HCH_5670MHz_Ant1_NTNV




802.11n(HT40)_HCH_5670MHz_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 170 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 171 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 172 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 173 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 174 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 175 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 176 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 177 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 178 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 179 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 180 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 181 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 182 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 183 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 184 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 185 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 186 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 187 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 188 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 189 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 190 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 191 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 192 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 193 of 1085







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 194 of 1085

802.11ax(HEW20)_HCH_5240MHz_SU_/_Ant1_NTNV




802.11ax(HEW20)_HCH_5240MHz_SU_/_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 195 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 196 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 197 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 198 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 199 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 200 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 201 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 202 of 1085




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
 Rev.: 01
 Page: 203 of 1085

802.11ax(HEW40)_LCH_5270MHz_SU_/_Ant1_NTNV




802.11ax(HEW40)_LCH_5270MHz_SU_/_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 204 of 1085




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
 Rev.: 01
 Page: 205 of 1085

802.11ax(HEW40)_LCH_5510MHz_SU_/_Ant1_NTNV




802.11ax(HEW40)_LCH_5510MHz_SU_/_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 206 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 207 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 208 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 209 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 210 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 211 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 212 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 213 of 1085






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 214 of 1085


2.2.3 6dB BW





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 215 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 216 of 1085







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 217 of 1085

802.11n(HT20)_LCH_5745MHz_Ant1_NTNV




802.11n(HT20)_LCH_5745MHz_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 218 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 219 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 220 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 221 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 222 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 223 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 224 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 225 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 226 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 227 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 228 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 229 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 230 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 231 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 232 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 233 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004

Rev.: 01

Page: 234 of 1085

3. Maximum Conducted Output Power

3.1 Test Result

3.1.1 Power

Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum Average Conducted Output Power (dBm)				Verdict
					ANT1	ANT2	MIMO	Limit	
802.11a	MIMO	5180	/	/	17.79	17.01	20.43	<=23.98	Pass
		5200	/	/	18.28	16.91	20.66	<=23.98	Pass
		5240	/	/	18.05	17.09	20.61	<=23.98	Pass
		5260	/	/	18.16	16.74	20.52	<=23.82	Pass
		5300	/	/	18.12	16.47	20.38	<=23.82	Pass
		5320	/	/	18.03	16.78	20.46	<=23.85	Pass
		5500	/	/	18.03	16.30	20.26	<=23.83	Pass
		5580	/	/	18.58	16.66	20.74	<=23.81	Pass
		5700	/	/	18.41	16.71	20.65	<=23.83	Pass
		5745	/	/	18.31	16.59	20.54	<=30	Pass
		5785	/	/	18.22	16.76	20.56	<=30	Pass
		5825	/	/	18.03	16.27	20.25	<=30	Pass
802.11n (HT20)	MIMO	5180	/	/	17.87	18.03	20.96	<=23.98	Pass
		5200	/	/	16.45	17.14	19.82	<=23.98	Pass
		5240	/	/	16.39	17.02	19.73	<=23.98	Pass
		5260	/	/	17.82	18.54	21.21	<=23.98	Pass
		5300	/	/	16.36	16.88	19.64	<=23.98	Pass
		5320	/	/	16.68	16.85	19.78	<=23.98	Pass
		5500	/	/	16.41	17.72	20.12	<=23.98	Pass
		5580	/	/	16.29	17.92	20.19	<=23.98	Pass
		5700	/	/	16.13	17.63	19.95	<=23.98	Pass
		5745	/	/	16.20	17.68	20.01	<=30	Pass
		5785	/	/	16.38	17.78	20.15	<=30	Pass
		5825	/	/	16.06	17.55	19.88	<=30	Pass
802.11n (HT40)	MIMO	5190	/	/	17.49	18.28	20.91	<=23.98	Pass
		5230	/	/	17.34	18.62	21.04	<=23.98	Pass
		5270	/	/	17.45	18.71	21.14	<=23.98	Pass
		5310	/	/	17.68	18.18	20.95	<=23.98	Pass
		5510	/	/	17.54	19.00	21.34	<=23.98	Pass
		5550	/	/	17.54	19.38	21.57	<=23.98	Pass
		5670	/	/	16.91	19.31	21.28	<=23.98	Pass
		5755	/	/	16.11	17.88	20.09	<=30	Pass
		5795	/	/	16.44	17.91	20.25	<=30	Pass
802.11ac (VHT20)	MIMO	5180	/	/	17.76	17.91	20.85	<=23.98	Pass
		5200	/	/	17.63	18.37	21.03	<=23.98	Pass
		5240	/	/	17.66	18.33	21.02	<=23.98	Pass
		5260	/	/	16.47	17.22	19.87	<=23.98	Pass
		5300	/	/	16.33	16.88	19.62	<=23.98	Pass
		5320	/	/	16.63	16.85	19.75	<=23.98	Pass
		5500	/	/	16.37	17.63	20.06	<=23.98	Pass
		5580	/	/	16.12	17.97	20.15	<=23.98	Pass
		5700	/	/	16.16	17.58	19.94	<=23.98	Pass
		5745	/	/	16.10	16.01	19.07	<=30	Pass
		5785	/	/	16.40	16.84	19.64	<=30	Pass
		5825	/	/	16.27	16.63	19.46	<=30	Pass
802.11ac (VHT40)	MIMO	5190	/	/	17.49	18.24	20.89	<=23.98	Pass
		5230	/	/	17.18	18.50	20.90	<=23.98	Pass
		5270	/	/	17.44	18.59	21.06	<=23.98	Pass



SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004

Rev.: 01

Page: 235 of 1085

		5310	/	/	17.60	18.02	20.83	<=23.98	Pass
		5510	/	/	17.41	18.81	21.18	<=23.98	Pass
		5550	/	/	17.37	19.19	21.38	<=23.98	Pass
		5670	/	/	16.79	19.03	21.06	<=23.98	Pass
		5755	/	/	17.14	15.86	19.56	<=30	Pass
		5795	/	/	16.91	15.75	19.38	<=30	Pass
802.11ac (VHT80)	MIMO	5210	/	/	17.17	18.34	20.80	<=23.98	Pass
		5290	/	/	17.39	18.29	20.87	<=23.98	Pass
		5530	/	/	17.20	18.61	20.97	<=23.98	Pass
		5610	/	/	17.05	19.29	21.32	<=23.98	Pass
		5775	/	/	16.10	17.47	19.85	<=30	Pass
802.11ac (VHT160)	MIMO	5570	/	/	16.67	18.59	20.75	<=23.98	Pass
		5250	/	/	12.06	12.04	15.06	<=23.98	Pass
802.11ax (HEW20)	MIMO	5180	SU	/	16.64	16.45	19.56	<=23.98	Pass
		5200	SU	/	16.42	16.91	19.68	<=23.98	Pass
		5240	SU	/	16.36	16.87	19.63	<=23.98	Pass
		5260	SU	/	16.48	17.07	19.80	<=23.98	Pass
		5300	SU	/	16.29	16.64	19.48	<=23.98	Pass
		5320	SU	/	16.55	16.53	19.55	<=23.98	Pass
		5500	SU	/	16.16	17.39	19.83	<=23.98	Pass
		5580	SU	/	15.95	17.82	20.00	<=23.98	Pass
		5700	SU	/	16.11	17.47	19.85	<=23.98	Pass
		5745	SU	/	16.20	17.50	19.91	<=30	Pass
		5785	SU	/	16.36	17.52	19.99	<=30	Pass
		5825	SU	/	16.27	17.27	19.81	<=30	Pass
802.11ax (HEW40)	MIMO	5190	SU	/	17.56	18.30	20.96	<=23.98	Pass
		5230	SU	/	17.36	18.47	20.96	<=23.98	Pass
		5270	SU	/	17.46	18.56	21.06	<=23.98	Pass
		5310	SU	/	17.70	18.07	20.90	<=23.98	Pass
		5510	SU	/	17.52	18.79	21.21	<=23.98	Pass
		5550	SU	/	17.55	19.13	21.42	<=23.98	Pass
		5670	SU	/	17.03	19.13	21.22	<=23.98	Pass
		5755	SU	/	16.17	17.54	19.92	<=30	Pass
		5795	SU	/	16.39	17.49	19.99	<=30	Pass
802.11ax (HEW80)	MIMO	5210	SU	/	16.51	17.42	20.00	<=23.98	Pass
		5290	SU	/	16.28	17.43	19.90	<=23.98	Pass
		5530	SU	/	16.29	17.91	20.19	<=23.98	Pass
		5610	SU	/	16.25	18.36	20.44	<=23.98	Pass
		5775	SU	/	16.28	17.59	19.99	<=30	Pass
802.11ax (HEW160)	MIMO	5570	SU	/	16.68	18.61	20.76	<=23.98	Pass
		5250	SU	/	12.39	12.37	15.39	<=23.98	Pass




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 236 of 1085

3.2 Test Graph


3.2.1 Power





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 237 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 238 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 239 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 240 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 241 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 242 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 243 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 244 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 245 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 246 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 247 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 248 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 249 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 250 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 251 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 252 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 253 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 254 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 255 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 256 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 257 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 258 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 259 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 260 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 261 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 262 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 263 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 264 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 265 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 266 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 267 of 1085







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 268 of 1085

802.11n(HT40)_HCH_5795MHz_Ant1_NTNV




802.11n(HT40)_HCH_5795MHz_Ant2_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 269 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 270 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 271 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 272 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 273 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 274 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 275 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 276 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 277 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 278 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 279 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 280 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 281 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 282 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 283 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 284 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 285 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 286 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 287 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250300017004
Rev.: 01
Page: 288 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 289 of 1085





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250300017004
Rev.: 01
Page: 290 of 1085

