



H-Field Position B




H-Field Position C



H-Field Position D




H-Field Position E



M5:


E-Field Position A



E-Field Position B



E-Field Position C




E-Field Position D



E-Field Position E




H-Field Position A



H-Field Position B




H-Field Position C



H-Field Position D




H-Field Position E



M6:

E-Field Position A



E-Field Position B




E-Field Position C




E-Field Position D



E-Field Position E




H-Field Position A



H-Field Position B



H-Field Position C



H-Field Position D



H-Field Position E

