





OBW NVNT ac20 5180MHz Ant1



Date: 22.OCT.2024 10:50:09


OBW NVNT ac20 5200MHz Ant1



Date: 23.OCT.2024 16:32:52




OBW NVNT ac20 5240MHz Ant1



Date: 22.OCT.2024 10:54:25


OBW NVNT ac20 5180MHz Ant2



Date: 22.OCT.2024 18:01:36




OBW NVNT ac20 5200MHz Ant2



Date: 23.OCT.2024 17:44:39


OBW NVNT ac20 5240MHz Ant2



Date: 22.OCT.2024 18:02:49




OBW NVNT ac20 5260MHz Ant1



Date: 23.OCT.2024 16:34:35


OBW NVNT ac20 5300MHz Ant1



Date: 23.OCT.2024 16:36:08




OBW NVNT ac20 5320MHz Ant1



Date: 28.OCT.2024 07:58:53


OBW NVNT ac20 5500MHz Ant1



Date: 24.OCT.2024 17:01:37




OBW NVNT ac20 5580MHz Ant1



Date: 24.OCT.2024 17:02:55


OBW NVNT ac20 5700MHz Ant1



Date: 24.OCT.2024 17:05:05




OBW NVNT ac20 5720MHz Ant1



Date: 24.OCT.2024 17:08:13


OBW NVNT ac20 5260MHz Ant2



Date: 23.OCT.2024 17:45:47




OBW NVNT ac20 5300MHz Ant2



Date: 23.OCT.2024 17:47:14


OBW NVNT ac20 5320MHz Ant2



Date: 28.OCT.2024 08:08:08




OBW NVNT ac20 5500MHz Ant2



Date: 24.OCT.2024 19:07:32


OBW NVNT ac20 5580MHz Ant2



Date: 24.OCT.2024 19:08:50




OBW NVNT ac20 5700MHz Ant2



Date: 24.OCT.2024 19:10:19


OBW NVNT ac20 5720MHz Ant2




Date: 24.OCT.2024 19:12:08



OBW NVNT ac20 5745MHz Ant1




OBW NVNT ac20 5785MHz Ant1






OBW NVNT ac20 5825MHz Ant1



Date: 25.OCT.2024 10:55:50


OBW NVNT ac20 5745MHz Ant2



Date: 25.OCT.2024 11:47:56




OBW NVNT ac20 5785MHz Ant2



Date: 25.OCT.2024 13:34:27


OBW NVNT ac20 5825MHz Ant2



Date: 25.OCT.2024 13:38:27




OBW NVNT ac40 5190MHz Ant1



Date: 22.OCT.2024 11:17:25


OBW NVNT ac40 5230MHz Ant1



Date: 22.OCT.2024 11:20:53




OBW NVNT ac40 5190MHz Ant2



Date: 22.OCT.2024 19:11:44


OBW NVNT ac40 5230MHz Ant2



Date: 22.OCT.2024 19:12:45




OBW NVNT ac40 5270MHz Ant1



Date: 23.OCT.2024 17:03:04


OBW NVNT ac40 5310MHz Ant1



Date: 23.OCT.2024 17:04:22




OBW NVNT ac40 5510MHz Ant1



Date: 24.OCT.2024 17:33:05


OBW NVNT ac40 5550MHz Ant1



Date: 24.OCT.2024 17:36:30




OBW NVNT ac40 5670MHz Ant1



Date: 24.OCT.2024 17:38:38


OBW NVNT ac40 5710MHz Ant1



Date: 24.OCT.2024 17:41:18




OBW NVNT ac40 5270MHz Ant2



Date: 23.OCT.2024 18:57:03


OBW NVNT ac40 5310MHz Ant2



Date: 23.OCT.2024 18:58:01




OBW NVNT ac40 5510MHz Ant2



Date: 25.OCT.2024 09:04:48


OBW NVNT ac40 5550MHz Ant2



Date: 25.OCT.2024 09:05:56




OBW NVNT ac40 5670MHz Ant2



Date: 25.OCT.2024 09:06:58


OBW NVNT ac40 5710MHz Ant2



Date: 25.OCT.2024 09:07:58




OBW NVNT ac40 5755MHz Ant1



Date: 25.OCT.2024 11:12:32


OBW NVNT ac40 5795MHz Ant1



Date: 25.OCT.2024 11:14:12




OBW NVNT ac40 5755MHz Ant2



Date: 25.OCT.2024 13:59:24


OBW NVNT ac40 5795MHz Ant2



Date: 25.OCT.2024 14:00:37




OBW NVNT ac80 5210MHz Ant1



Date: 23.OCT.2024 10:40:30


OBW NVNT ac80 5290MHz Ant1



Date: 23.OCT.2024 10:45:37




OBW NVNT ac80 5210MHz Ant2



Date: 23.OCT.2024 11:15:54


OBW NVNT ac80 5290MHz Ant2



Date: 23.OCT.2024 11:18:09




OBW NVNT ac80 5530MHz Ant1



Date: 23.OCT.2024 17:16:31


OBW NVNT ac80 5610MHz Ant1



Date: 23.OCT.2024 17:18:00




OBW NVNT ac80 5690MHz Ant1



Date: 23.OCT.2024 17:19:34


OBW NVNT ac80 5530MHz Ant2



Date: 23.OCT.2024 19:09:17




OBW NVNT ac80 5610MHz Ant2



Date: 23.OCT.2024 19:11:16


OBW NVNT ac80 5690MHz Ant2



Date: 23.OCT.2024 19:13:16




OBW NVNT ac80 5775MHz Ant1



Date: 25.OCT.2024 11:18:27


OBW NVNT ac80 5775MHz Ant2



Date: 25.OCT.2024 14:05:45




OBW NVNT ax20 5180MHz Ant1




Date: 22 OCT 2024 11:00:07

OBW NVNT ax20 5200MHz Ant1




Date: 23 OCT 2024 16:37:51

OBW NVNT ax20 5240MHz Ant1




OBW NVNT ax20 5180MHz Ant2






OBW NVNT ax20 5200MHz Ant2



Date: 23.OCT.2024 17:49:10


OBW NVNT ax20 5240MHz Ant2



Date: 22.OCT.2024 18:45:37




OBW NVNT ax20 5260MHz Ant1



Date: 23.OCT.2024 16:39:08


OBW NVNT ax20 5300MHz Ant1



Date: 23.OCT.2024 16:43:07




OBW NVNT ax20 5320MHz Ant1



Date: 28.OCT.2024 08:00:33


OBW NVNT ax20 5500MHz Ant1



Date: 24.OCT.2024 17:21:02




OBW NVNT ax20 5580MHz Ant1



Date: 24.OCT.2024 17:18:55


OBW NVNT ax20 5700MHz Ant1



Date: 24.OCT.2024 17:16:44




OBW NVNT ax20 5720MHz Ant1



Date: 24.OCT.2024 17:24:07


OBW NVNT ax20 5260MHz Ant2



Date: 23.OCT.2024 17:50:31




OBW NVNT ax20 5300MHz Ant2



Date: 23.OCT.2024 17:53:41


OBW NVNT ax20 5320MHz Ant2



Date: 28.OCT.2024 08:09:39




OBW NVNT ax20 5500MHz Ant2



Date: 24.OCT.2024 19:21:49


OBW NVNT ax20 5580MHz Ant2



Date: 24.OCT.2024 19:19:31




OBW NVNT ax20 5700MHz Ant2



Date: 24.OCT.2024 19:18:30


OBW NVNT ax20 5720MHz Ant2



Date: 25.OCT.2024 08:56:41




OBW NVNT ax20 5745MHz Ant1



Date: 25.OCT.2024 11:01:50


OBW NVNT ax20 5785MHz Ant1



Date: 25.OCT.2024 11:04:24




OBW NVNT ax20 5825MHz Ant1



Date: 25.OCT.2024 11:06:27


OBW NVNT ax20 5745MHz Ant2



Date: 25.OCT.2024 13:47:28




OBW NVNT ax20 5785MHz Ant2



Date: 25.OCT.2024 13:49:27


OBW NVNT ax20 5825MHz Ant2



Date: 25.OCT.2024 13:53:22




OBW NVNT ax40 5190MHz Ant1



Date: 22.OCT.2024 11:24:16


OBW NVNT ax40 5230MHz Ant1



Date: 22.OCT.2024 11:27:50




OBW NVNT ax40 5190MHz Ant2



Date: 22.OCT.2024 19:09:06


OBW NVNT ax40 5230MHz Ant2



Date: 22.OCT.2024 19:05:42




OBW NVNT ax40 5270MHz Ant1



Date: 23.OCT.2024 17:08:37


OBW NVNT ax40 5310MHz Ant1



Date: 23.OCT.2024 17:10:12




OBW NVNT ax40 5510MHz Ant1



Date: 24.OCT.2024 18:02:37


OBW NVNT ax40 5550MHz Ant1



Date: 24.OCT.2024 18:00:14




OBW NVNT ax40 5670MHz Ant1



Date: 24.OCT.2024 17:57:07


OBW NVNT ax40 5710MHz Ant1



Date: 24.OCT.2024 17:59:15




OBW NVNT ax40 5270MHz Ant2



Date: 23.OCT.2024 19:02:17


OBW NVNT ax40 5310MHz Ant2



Date: 23.OCT.2024 19:05:00




OBW NVNT ax40 5510MHz Ant2



Date: 25.OCT.2024 09:09:19


OBW NVNT ax40 5550MHz Ant2



Date: 25.OCT.2024 09:10:29




OBW NVNT ax40 5670MHz Ant2



Date: 25.OCT.2024 09:12:04


OBW NVNT ax40 5710MHz Ant2



Date: 25.OCT.2024 09:13:15




OBW NVNT ax40 5755MHz Ant1



Date: 25.OCT.2024 11:15:33


OBW NVNT ax40 5795MHz Ant1



Date: 25.OCT.2024 11:16:43




OBW NVNT ax40 5755MHz Ant2



Date: 25.OCT.2024 14:02:14


OBW NVNT ax40 5795MHz Ant2



Date: 25.OCT.2024 14:03:42




OBW NVNT ax80 5210MHz Ant1



Date: 23.OCT.2024 10:50:40


OBW NVNT ax80 5290MHz Ant1



Date: 23.OCT.2024 10:52:21




OBW NVNT ax80 5210MHz Ant2



Date: 23.OCT.2024 11:21:03


OBW NVNT ax80 5290MHz Ant2



Date: 23.OCT.2024 11:22:10




OBW NVNT ax80 5530MHz Ant1



Date: 23.OCT.2024 17:22:41


OBW NVNT ax80 5610MHz Ant1



Date: 23.OCT.2024 17:24:26




OBW NVNT ax80 5690MHz Ant1



Date: 23.OCT.2024 17:27:17


OBW NVNT ax80 5530MHz Ant2



Date: 23.OCT.2024 19:15:01




OBW NVNT ax80 5610MHz Ant2



Date: 23.OCT.2024 19:16:45


OBW NVNT ax80 5690MHz Ant2



Date: 23.OCT.2024 19:18:18




OBW NVNT ax80 5775MHz Ant1



Date: 25.OCT.2024 11:19:44


OBW NVNT ax80 5775MHz Ant2



Date: 25.OCT.2024 14:07:23




OBW NVNT ax160 5250MHz Ant1



Date: 23.OCT.2024 11:08:39


OBW NVNT ax160 5570MHz Ant1



Date: 23.OCT.2024 11:08:58




OBW NVNT ax160 5250MHz Ant2



Date: 23.OCT.2024 15:01:26

OBW NVNT ax160 5570MHz Ant2



Date: 23.OCT.2024 15:03:11