



1000 Marietta Street, Suite 244

Atlanta, GA 30318

January 3, 2020

Letter of Attestation

Model: Sensor-2 (FCC ID: 2AIJ5-SENSOR2)

This letter attests to the fact that the Bastille Sensor-2 scanning receiver meets the requirements of FCC 47 CFR § 15.121(a) by the following features:

1. Band blocking mechanisms are embedded in firmware
2. Firmware is secured and are not available to users

These safeguards ensure the Bastille Sensor-2 is incapable of operating or readily being altered by the user to operate within the frequency bands allocated to the Cellular Radiotelephone Service.

Respectfully,

A handwritten signature in black ink, appearing to read "Bob Baxley", written over a horizontal line.

Bob Baxley, CTO, Bastille