



1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:11:05

1.4MHz_Middle_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:11:14

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:39:14

1.4MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:39:24

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:12:13

1.4MHz_High_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:12:22

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:40:24

3MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:40:34

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:14:06

3MHz_Low_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:14:15

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:54:41

3MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:54:51

3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:15:16

3MHz_Middle_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:15:26

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:41:36

3MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:41:47

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:16:29

3MHz_High_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:16:38

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:43:10

5MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:43:21

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:18:28

5MHz_Low_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:18:37

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:55:11

5MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:55:22

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:19:42

5MHz_Middle_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:19:52

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:44:35

5MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:44:46

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:20:58

5MHz_High_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:21:10

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:45:45

10MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:45:56

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:23:02

10MHz_Low_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:23:12

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:46:09

10MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:46:20

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:24:23

10MHz_Middle_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:24:33

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:56:03

10MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 11:56:15

10MHz_High_QPSK_50@0(30MHz~1GHz)



ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:25:42

10MHz_High_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 16:25:52

LTE B26_2, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:09:10

1.4MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:09:22

1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:32:05

1.4MHz_Low_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:32:20

1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:23:19

1.4MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:23:31

1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:34:05

1.4MHz_Middle_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:34:19

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:10:21

1.4MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:10:31

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:36:05

1.4MHz_High_QPSK_6@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:36:19

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:11:13

3MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:11:23

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:38:54

3MHz_Low_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:39:11

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:24:13

3MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:24:25

3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:41:06

3MHz_Middle_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:41:23

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:12:26

3MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:12:38

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:43:12

3MHz_High_QPSK_15@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:43:28

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:13:19

5MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:13:30

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:46:00

5MHz_Low_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:46:15

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:25:09

5MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:25:22

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:48:06

5MHz_Middle_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:48:21

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:14:27

5MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:14:38

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:50:21

5MHz_High_QPSK_25@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:50:39

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:15:19

10MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:15:31

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:53:22

10MHz_Low_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:53:38

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:15:46

10MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:15:57

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:55:40

10MHz_Middle_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 26.MAY.2025 19:55:59

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:16:17

10MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:16:29

10MHz_High_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 09:42:09

10MHz_High_QPSK_50@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 09:42:16

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:17:10

15MHz_Low_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:17:22

15MHz_Low_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 09:43:26

15MHz_Low_QPSK_75@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 09:43:33

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:17:36

15MHz_Middle_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:17:49

15MHz_Middle_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 09:44:13

15MHz_Middle_QPSK_75@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 09:44:19

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:18:03

15MHz_High_QPSK_1@0(1GHz~9.49GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 13:18:15

15MHz_High_QPSK_75@0(30MHz~1GHz)



ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 09:48:07

15MHz_High_QPSK_75@0(1GHz~9.49GHz)



ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 09:48:14