




20MHz_High_QPSK_1@0(30MHz~1GHz)




20MHz_High_QPSK_1@0(1GHz~27.2GHz)



20MHz_High_QPSK_100@0(30MHz~1GHz)




20MHz_High_QPSK_100@0(1GHz~27.2GHz)




LTE Band 66, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~1GHz)



1.4MHz_Low_QPSK_1@0(1GHz~18.8GHz)




1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:09:38

1.4MHz_Low_QPSK_6@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:09:49

1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:03:37

1.4MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:03:47

1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:10:43

1.4MHz_Middle_QPSK_6@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:10:53

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:03:56

1.4MHz_High_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:04:06

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:11:44

1.4MHz_High_QPSK_6@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:11:56

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:05:03

3MHz_Low_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:05:14

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:13:35

3MHz_Low_QPSK_15@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:13:46

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:05:23

3MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:05:34

3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:14:39

3MHz_Middle_QPSK_15@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:14:50

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:05:42

3MHz_High_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:05:53

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:15:45

3MHz_High_QPSK_15@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:15:56

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:06:52

5MHz_Low_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:07:03

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:17:39

5MHz_Low_QPSK_25@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:17:50

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:07:12

5MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:07:23

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:18:47

5MHz_Middle_QPSK_25@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:18:58

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:07:32

5MHz_High_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:07:42

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:19:55

5MHz_High_QPSK_25@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:20:06

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:08:40

10MHz_Low_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:08:51

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:21:55

10MHz_Low_QPSK_50@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:22:07

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:09:00

10MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:09:11

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:23:06

10MHz_Middle_QPSK_50@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:23:18

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:09:20

10MHz_High_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:09:31

10MHz_High_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:24:18

10MHz_High_QPSK_50@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:24:31

15MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:10:10

15MHz_Low_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:10:21

15MHz_Low_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:26:14

15MHz_Low_QPSK_75@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:26:26

15MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:10:30

15MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:10:41

15MHz_Middle_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:27:28

15MHz_Middle_QPSK_75@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:27:40

15MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:10:51

15MHz_High_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:11:02

15MHz_High_QPSK_75@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:28:44

15MHz_High_QPSK_75@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:28:56

20MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:11:55

20MHz_Low_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:12:07

20MHz_Low_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:30:40

20MHz_Low_QPSK_100@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:30:53

20MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:12:16

20MHz_Middle_QPSK_1@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 21.AUG.2025 15:12:27

20MHz_Middle_QPSK_100@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:31:58

20MHz_Middle_QPSK_100@0(1GHz~18.8GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 27.MAY.2025 11:32:10


20MHz_High_QPSK_1@0(30MHz~1GHz)




20MHz_High_QPSK_1@0(1GHz~18.8GHz)



20MHz_High_QPSK_100@0(30MHz~1GHz)




20MHz_High_QPSK_100@0(1GHz~18.8GHz)




LTE B41_2, Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~1GHz)



5MHz_Low_QPSK_1@0(1GHz~27.55GHz)




5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:13:01

5MHz_Low_QPSK_25@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:13:16

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:18:33

5MHz_Middle_QPSK_1@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:18:47

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:19:09

5MHz_Middle_QPSK_25@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:19:22

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:19:44

5MHz_High_QPSK_1@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:19:57

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:20:18

5MHz_High_QPSK_25@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:20:31

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:21:01

10MHz_Low_QPSK_1@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:21:15

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:21:36

10MHz_Low_QPSK_50@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:21:49

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:22:11

10MHz_Middle_QPSK_1@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:22:25

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:23:49

10MHz_Middle_QPSK_50@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:24:32

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:25:21

10MHz_High_QPSK_1@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:25:35

10MHz_High_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:25:59

10MHz_High_QPSK_50@0(1GHz~27.55GHz)




ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:26:13

15MHz_Low_QPSK_1@0(30MHz~1GHz)



ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:26:39

15MHz_Low_QPSK_1@0(1GHz~27.55GHz)



ProjectNo.:2504S23848E-RF Tester:Benny Li
Date: 2.JUN.2025 14:26:52