




Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)



Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:44:42

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:45:04

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:45:33

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:45:56


Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)



Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:47:36

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:47:58

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:48:27

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:48:50

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:49:29

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:49:51

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:50:27

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:50:52

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:51:28

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:51:57

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:52:28

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:52:53

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:53:27

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 28.OCT.2021 15:53:46

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:54:18

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 15:54:43

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:55:13

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 15:55:39

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:56:11

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 15:56:34

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:57:01

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 15:57:30

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:57:57

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 15:58:20

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:58:47

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 15:59:13

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 15:59:45

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 16:00:10

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:00:46

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 16:01:09

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:01:36

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 16:01:58

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:02:30

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 16:02:55

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:03:25

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 16:03:51

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:04:27

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 16:04:52

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:05:21

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 28.OCT.2021 16:05:49

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:06:19

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 28.OCT.2021 16:06:41

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:07:11

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 28.OCT.2021 16:07:43

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:08:09

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 28.OCT.2021 16:08:35

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:09:02

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 28.OCT.2021 16:09:25

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 16:09:59

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 28.OCT.2021 16:10:21

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:00:55

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:01:27

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:01:56

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:02:19

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:02:45

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:03:08

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:03:37

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:04:02

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:04:30

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:05:01

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:05:26

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:05:51

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:06:26

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:06:52

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:07:34

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:07:56

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:08:29

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:08:57

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:09:32

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:09:58

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:10:30

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:10:59

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 28.OCT.2021 17:11:32

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 17:11:54

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:16:09

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:16:32

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:16:58

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:17:21

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:17:44

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:18:06

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:18:36

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:19:04

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:19:35

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:20:01

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:20:28

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:20:54

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:21:29

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:21:48

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:22:18

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:22:43

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:23:13

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:23:39

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:24:14

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:24:36

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 28.OCT.2021 18:25:15

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 28.OCT.2021 18:25:44

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 28.OCT.2021 18:26:11

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 28.OCT.2021 18:26:39