



10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:36:45

10MHz_Middle_QPSK_50@0(1GHz~8.16GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 21:59:11

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:36:53

10MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 21:59:42

10MHz_High_QPSK_50@0(30MHz~1GHz)



ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:37:01


10MHz_High_QPSK_50@0(1GHz~8.16GHz)



ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:00:14


B17, Normal

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:37:49

5MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:02:31

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:37:58

5MHz_Low_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:03:02

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:38:06

5MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:03:33


5MHz_Middle_QPSK_25@0(30MHz~1GHz)




5MHz_Middle_QPSK_25@0(1GHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~1GHz)




5MHz_High_QPSK_1@0(1GHz~8.16GHz)




5MHz_High_QPSK_25@0(30MHz~1GHz)




5MHz_High_QPSK_25@0(1GHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~1GHz)




10MHz_Low_QPSK_1@0(1GHz~8.16GHz)




10MHz_Low_QPSK_50@0(30MHz~1GHz)




10MHz_Low_QPSK_50@0(1GHz~8.16GHz)




10MHz_Middle_QPSK_1@0(30MHz~1GHz)



10MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:41:22

10MHz_Middle_QPSK_50@0(1GHz~8.16GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:11:07

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:41:30

10MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:11:39

10MHz_High_QPSK_50@0(30MHz~1GHz)



ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 15.APR.2025 21:41:37


10MHz_High_QPSK_50@0(1GHz~8.16GHz)



ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:12:12


B38, Normal

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Ueain Ou
Date: 16.MAR.2025 22:13:19

5MHz_Low_QPSK_1@0(1GHz~27.2GHz)




ProjectNo.:2401A109741E-RF Tester:Ueain Ou
Date: 16.MAR.2025 22:13:35

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Ueain Ou
Date: 16.MAR.2025 22:13:55

5MHz_Low_QPSK_25@0(1GHz~27.2GHz)




ProjectNo.:2401A109741E-RF Tester:Ueain Ou
Date: 16.MAR.2025 22:14:10

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Ueain Ou
Date: 16.MAR.2025 22:14:30

5MHz_Middle_QPSK_1@0(1GHz~27.2GHz)




ProjectNo.:2401A109741E-RF Tester:Ueain Ou
Date: 16.MAR.2025 22:14:46

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:15:06

5MHz_Middle_QPSK_25@0(1GHz~27.2GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:15:21

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:15:42

5MHz_High_QPSK_1@0(1GHz~27.2GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:15:59

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:16:20

5MHz_High_QPSK_25@0(1GHz~27.2GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:16:36

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:17:38

10MHz_Low_QPSK_1@0(1GHz~27.2GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:17:53

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:18:13

10MHz_Low_QPSK_50@0(1GHz~27.2GHz)




ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:18:28

10MHz_Middle_QPSK_1@0(30MHz~1GHz)



ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:18:48

10MHz_Middle_QPSK_1@0(1GHz~27.2GHz)



ProjectNo.:2401A109741E-RF Tester:Usain Ou
Date: 16.MAR.2025 22:19:04