



n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.63dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:11:11

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@50
-38.93dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:11:57

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0
-38.80dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:12:45

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0
-38.90dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:13:35

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@50
-38.74dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:14:21

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB50@0
-39.02dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:15:03

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0
-38.44dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:15:55

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@77
-38.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:16:40

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB75@0
-38.71dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:17:26

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.47dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:18:14

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@77
-38.60dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:18:59

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB75@0
-38.80dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:19:44

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@0
-37.83dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:20:32

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@77
-38.69dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:21:17

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB75@0
-38.78dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:22:01

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0
-38.66dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:22:51

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -39.14dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:23:36

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -38.88dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:24:21

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.91dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:25:08

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -38.72dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:25:53

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -38.43dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:26:39

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0
-38.84dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:27:26

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -38.37dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:28:11

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -38.60dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:28:55

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0
-38.75dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:29:45

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -38.92dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:30:29

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -38.31dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:31:14

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.47dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:32:01

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -38.54dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:32:46

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -37.89dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:33:30

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0
-38.69dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:34:17

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -38.99dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:35:02

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -38.96dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:35:46

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0
-38.70dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:36:34

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -38.53dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:37:18

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -39.20dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:38:04

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.79dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:38:51

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -38.54dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:39:35

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -38.52dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:40:20

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@0
-38.75dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:41:07

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -38.71dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:41:54

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -37.71dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:42:44

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0
-39.16dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:43:37

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -38.92dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:44:23

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -38.78dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:45:10

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.50dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:46:03

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -38.77dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:47:06

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -38.22dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:47:53

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0
-38.52dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:48:42

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -38.90dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:49:29

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -38.95dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:50:15

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0
-38.78dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:51:05

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@216 -38.62dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:51:51

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -38.76dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:52:38

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.83dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:53:30

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@216 -38.20dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:54:17

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0 -38.51dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:55:03

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@0
-38.87dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:55:50

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -38.83dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:56:34

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -38.62dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 22:57:19


n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0
-38.75dBm




n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@244 -38.94dBm




n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -38.12dBm




n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.80dBm




n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@244 -38.73dBm



n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB243@0 -38.15dBm




n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@0
-38.34dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:02:43

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244 -38.80dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:03:28

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0 -38.94dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:04:13

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.40dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:05:15

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@272 -38.42dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:06:00


n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB270@0 -38.54dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 4.MAY.2025 23:06:46

n78_3


n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@0
-36.51dBm




n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB1@23
-36.33dBm




n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM QPSK_RB24@0
-37.21dBm




n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-35.95dBm




n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@23
-35.65dBm




n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB24@0
-36.47dBm




n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB1@0
-36.62dBm




n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB1@23
-36.70dBm




n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM QPSK_RB24@0
-35.39dBm




n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.50dBm




n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -36.95dBm



n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -36.86dBm




n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.34dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:40:36

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@37
-36.48dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:41:23

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB36@0
-36.63dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:42:09

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.49dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:43:00

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@37 -36.30dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:43:50

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB36@0 -36.55dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:44:39

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@0
-36.74dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:45:32

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB1@50
-36.80dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:46:25

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM QPSK_RB50@0
-36.52dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:47:15

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.63dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:48:15

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@50
-36.44dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:49:04

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB50@0
-36.39dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:49:52

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM QPSK_RB1@0
-36.90dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:50:44

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM QPSK_RB1@50
-36.37dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:51:32

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM QPSK_RB50@0
-36.90dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:52:21

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0
-36.99dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:53:24

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@77
-36.68dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:54:13

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0
-36.69dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:55:02

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.49dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:55:54

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@77
-36.78dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:56:43

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0
-37dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:57:31

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0
-36.50dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:58:22

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77
-36.90dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:59:11

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0
-36.95dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 00:59:59