




n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0
-36.20dBm




n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@105 -36.52dBm




n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -36.58dBm




n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.38dBm




n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@105 -36.49dBm



n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB100@0 -36.36dBm




n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0
-36.06dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:05:40

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105 -37.16dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:06:27

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0 -36.96dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:07:13

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0
-36.95dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:08:03

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@132 -36.89dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:08:50

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -36.72dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:09:33

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.81dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:10:25

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@132 -36.97dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:11:11

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB128@0 -36.01dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:11:57

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0
-36.64dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:12:46

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@132 -36.58dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:13:32

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0 -36.69dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:14:18

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0
-36.66dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:15:09

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@161 -36.71dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:15:55

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -36.99dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:16:42

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.58dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:17:31

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@161 -35.47dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:18:18

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB162@0 -36.29dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:19:03

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@0
-36.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:19:54

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@161 -36.78dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:20:40

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB162@0 -36.65dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:21:28

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0
-36.67dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:22:18

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@188 -36.90dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:23:05

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -36.33dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:23:52

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.87dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:24:41

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@188 -36.55dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:25:27

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB180@0 -36.10dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:26:14

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@0
-36.82dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:27:03

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@188 -36.87dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:27:50

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB180@0 -36.80dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:28:37


n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0
-36.30dBm




n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@216 -36.01dBm




n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -36.69dBm




n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.97dBm




n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@216 -36.77dBm



n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB216@0 -36.54dBm




n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM QPSK_RB1@0
-36.61dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:34:21

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@216 -36.73dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:35:08

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB216@0 -36.95dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:35:54

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM QPSK_RB1@0
-36.58dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:36:45

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@244 -36.54dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:37:32

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -36.58dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:38:19


n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.52dBm




n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@244 -36.73dBm




n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB243@0 -36.59dBm




n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM QPSK_RB1@0
-36.18dBm




n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@244 -36.24dBm



n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB243@0 -35.98dBm




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-36.88dBm




ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:44:12

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -37.01dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:45:02

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -36.74dBm



ProjectNo.:2501S22736E-RF Tester:Usain Ou
Date: 5.MAY.2025 01:45:51