





30MHz_15kHz_3625MHz_DFT-s-OFDM 64 QAM_RB160@0 28.582 MHz




30MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB160@0 28.486 MHz

30MHz_15kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB160@0 28.482 MHz


30MHz_30kHz_3625MHz_CP-OFDM 16 QAM_RB78@0 27.777 MHz




30MHz_30kHz_3625MHz_CP-OFDM 256 QAM_RB78@0 27.745 MHz




30MHz_30kHz_3625MHz_CP-OFDM 64 QAM_RB78@0 27.862 MHz




30MHz_30kHz_3625MHz_CP-OFDM QPSK_RB78@0 27.763 MHz




30MHz_30kHz_3625MHz_DFT-s-OFDM 16 QAM_RB75@0 27.615 MHz




30MHz_30kHz_3625MHz_DFT-s-OFDM 256 QAM_RB75@0 27.753 MHz




30MHz_30kHz_3625MHz_DFT-s-OFDM 64 QAM_RB75@0 27.514 MHz




30MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB75@0 27.534 MHz

30MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB75@0 27.648 MHz


40MHz_15kHz_3625MHz_CP-OFDM 16 QAM_RB216@0 38.460 MHz




40MHz_15kHz_3625MHz_CP-OFDM 256 QAM_RB216@0 38.467 MHz




40MHz_15kHz_3625MHz_CP-OFDM 64 QAM_RB216@0 38.561 MHz



40MHz_15kHz_3625MHz_CP-OFDM QPSK_RB216@0 38.460 MHz




40MHz_15kHz_3625MHz_DFT-s-OFDM 16 QAM_RB216@0 38.588 MHz





40MHz_15kHz_3625MHz_DFT-s-OFDM 256 QAM_RB216@0 38.590 MHz




40MHz_15kHz_3625MHz_DFT-s-OFDM 64 QAM_RB216@0 38.477 MHz




40MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB216@0 38.579 MHz

40MHz_15kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB216@0 38.597 MHz

40MHz_30kHz_3625MHz_CP-OFDM 16 QAM_RB106@0 37.764 MHz



40MHz_30kHz_3625MHz_CP-OFDM 256 QAM_RB106@0 37.818 MHz




40MHz_30kHz_3625MHz_CP-OFDM 64 QAM_RB106@0 37.806 MHz




40MHz_30kHz_3625MHz_CP-OFDM QPSK_RB106@0 37.675 MHz



40MHz_30kHz_3625MHz_DFT-s-OFDM 16 QAM_RB100@0 37.499 MHz




40MHz_30kHz_3625MHz_DFT-s-OFDM 256 QAM_RB100@0 37.658 MHz




40MHz_30kHz_3625MHz_DFT-s-OFDM 64 QAM_RB100@0 37.286 MHz




40MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB100@0 37.502 MHz

40MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB100@0 37.332 MHz


50MHz_15kHz_3625MHz_CP-OFDM 16 QAM_RB270@0 48.081 MHz




50MHz_15kHz_3625MHz_CP-OFDM 256 QAM_RB270@0 48.236 MHz




50MHz_15kHz_3625MHz_CP-OFDM 64 QAM_RB270@0 48.075 MHz




50MHz_15kHz_3625MHz_CP-OFDM QPSK_RB270@0 48.220 MHz




50MHz_15kHz_3625MHz_DFT-s-OFDM 16 QAM_RB270@0 48.086 MHz





50MHz_15kHz_3625MHz_DFT-s-OFDM 256 QAM_RB270@0 48.080 MHz




50MHz_15kHz_3625MHz_DFT-s-OFDM 64 QAM_RB270@0 48.100 MHz




50MHz_15kHz_3625MHz_DFT-s-OFDM QPSK_RB270@0 48.041 MHz

50MHz_15kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB270@0 48.236 MHz


50MHz_30kHz_3625MHz_CP-OFDM 16 QAM_RB133@0 47.266 MHz




50MHz_30kHz_3625MHz_CP-OFDM 256 QAM_RB133@0 47.280 MHz




50MHz_30kHz_3625MHz_CP-OFDM 64 QAM_RB133@0 47.456 MHz




50MHz_30kHz_3625MHz_CP-OFDM QPSK_RB133@0 47.400 MHz




50MHz_30kHz_3625MHz_DFT-s-OFDM 16 QAM_RB128@0 47.030 MHz




50MHz_30kHz_3625MHz_DFT-s-OFDM 256 QAM_RB128@0 46.898 MHz



50MHz_30kHz_3625MHz_DFT-s-OFDM 64 QAM_RB128@0 47.034 MHz




50MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB128@0 46.888 MHz

50MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB128@0 47.021 MHz

60MHz_30kHz_3625MHz_CP-OFDM 16 QAM_RB162@0 57.686 MHz



60MHz_30kHz_3625MHz_CP-OFDM 256 QAM_RB162@0 57.704 MHz




60MHz_30kHz_3625MHz_CP-OFDM 64 QAM_RB162@0 57.663 MHz



60MHz_30kHz_3625MHz_CP-OFDM QPSK_RB162@0 57.672 MHz




60MHz_30kHz_3625MHz_DFT-s-OFDM 16 QAM_RB162@0 57.925 MHz





60MHz_30kHz_3625MHz_DFT-s-OFDM 256 QAM_RB162@0 57.885 MHz




60MHz_30kHz_3625MHz_DFT-s-OFDM 64 QAM_RB162@0 57.704 MHz




60MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB162@0 57.858 MHz

60MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB162@0 57.632 MHz


70MHz_30kHz_3625MHz_CP-OFDM 16 QAM_RB189@0 68.075 MHz




70MHz_30kHz_3625MHz_CP-OFDM 256 QAM_RB189@0 68.379 MHz



70MHz_30kHz_3625MHz_CP-OFDM 64 QAM_RB189@0 68.075 MHz




70MHz_30kHz_3625MHz_CP-OFDM QPSK_RB189@0 67.467 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 13:47:52

70MHz_30kHz_3625MHz_DFT-s-OFDM 16 QAM_RB180@0 64.428 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 13:46:19

70MHz_30kHz_3625MHz_DFT-s-OFDM 256 QAM_RB180@0 64.732 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 13:47:19

70MHz_30kHz_3625MHz_DFT-s-OFDM 64 QAM_RB180@0 64.428 MHz




ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 13:46:48

70MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB180@0 64.732 MHz



ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 13:45:50


70MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB180@0 64.732 MHz

ProjectNo.:2401S71481E Tester:Jim Cheng
Date: 20.MAY.2024 13:45:10


80MHz_30kHz_3625MHz_CP-OFDM 16 QAM_RB217@0 77.254 MHz




80MHz_30kHz_3625MHz_CP-OFDM 256 QAM_RB217@0 77.220 MHz



80MHz_30kHz_3625MHz_CP-OFDM 64 QAM_RB217@0 77.228 MHz



80MHz_30kHz_3625MHz_CP-OFDM QPSK_RB217@0 77.185 MHz



80MHz_30kHz_3625MHz_DFT-s-OFDM 16 QAM_RB216@0 77.190 MHz



80MHz_30kHz_3625MHz_DFT-s-OFDM 256 QAM_RB216@0 77.122 MHz




80MHz_30kHz_3625MHz_DFT-s-OFDM 64 QAM_RB216@0 77.144 MHz




80MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB216@0 76.959 MHz

80MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB216@0 76.907 MHz


90MHz_30kHz_3625MHz_CP-OFDM 16 QAM_RB245@0 87.159 MHz




90MHz_30kHz_3625MHz_CP-OFDM 256 QAM_RB245@0 87.276 MHz




90MHz_30kHz_3625MHz_CP-OFDM 64 QAM_RB245@0 87.211 MHz




90MHz_30kHz_3625MHz_CP-OFDM QPSK_RB245@0 87.219 MHz



90MHz_30kHz_3625MHz_DFT-s-OFDM 16 QAM_RB243@0 87.195 MHz




90MHz_30kHz_3625MHz_DFT-s-OFDM 256 QAM_RB243@0 86.802 MHz




90MHz_30kHz_3625MHz_DFT-s-OFDM 64 QAM_RB243@0 87.165 MHz




90MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB243@0 86.813 MHz

90MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB243@0 86.830 MHz


100MHz_30kHz_3625MHz_CP-OFDM 16 QAM_RB273@0 97.210 MHz




100MHz_30kHz_3625MHz_CP-OFDM 256 QAM_RB273@0 97.257 MHz




100MHz_30kHz_3625MHz_CP-OFDM 64 QAM_RB273@0 96.989 MHz




100MHz_30kHz_3625MHz_CP-OFDM QPSK_RB273@0 97.208 MHz




100MHz_30kHz_3625MHz_DFT-s-OFDM 16 QAM_RB270@0 96.902 MHz




100MHz_30kHz_3625MHz_DFT-s-OFDM 256 QAM_RB270@0 96.583 MHz



100MHz_30kHz_3625MHz_DFT-s-OFDM 64 QAM_RB270@0 96.853 MHz



100MHz_30kHz_3625MHz_DFT-s-OFDM QPSK_RB270@0 96.564 MHz



100MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$ BPSK_RB270@0 96.486 MHz

