



10MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:35:48

10MHz_Low_QPSK_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:37:13

10MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:38:38

10MHz_Low_16QAM_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:40:03

10MHz_High_QPSK_1@49




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:41:30

10MHz_High_QPSK_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:42:55

10MHz_High_16QAM_1@49



ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:44:22

10MHz_High_16QAM_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:45:49


FCC Part 24E

LTE Band 2 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5



1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 17:55:40

1.4MHz_High_16QAM_6@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 17:56:09

3MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 17:56:46

3MHz_Low_QPSK_15@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 17:57:19

3MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 17:57:52

3MHz_Low_16QAM_15@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 17:58:24

3MHz_High_QPSK_1@14




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 17:58:56

3MHz_High_QPSK_15@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:03:21

3MHz_High_16QAM_1@14




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:03:56

3MHz_High_16QAM_15@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:04:30

5MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:05:07

5MHz_Low_QPSK_25@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:05:38

5MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:06:10

5MHz_Low_16QAM_25@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:06:41

5MHz_High_QPSK_1@24




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:07:13

5MHz_High_QPSK_25@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:07:46

5MHz_High_16QAM_1@24




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:08:19

5MHz_High_16QAM_25@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:08:51

10MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:09:39

10MHz_Low_QPSK_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:10:21

10MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:11:04

10MHz_Low_16QAM_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:11:46

10MHz_High_QPSK_1@49




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:12:27

10MHz_High_QPSK_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:13:09

10MHz_High_16QAM_1@49




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:13:51

10MHz_High_16QAM_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:14:32

15MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:15:26

15MHz_Low_QPSK_75@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:16:16

15MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:17:05

15MHz_Low_16QAM_75@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:17:55

15MHz_High_QPSK_1@74




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:18:44

15MHz_High_QPSK_75@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:19:35

15MHz_High_16QAM_1@74




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:20:26

15MHz_High_16QAM_75@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:21:18

20MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:22:25

20MHz_Low_QPSK_100@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:23:28

20MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:24:31

20MHz_Low_16QAM_100@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:25:34

20MHz_High_QPSK_1@99




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:26:37

20MHz_High_QPSK_100@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:27:40

20MHz_High_16QAM_1@99



ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:28:43

20MHz_High_16QAM_100@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:29:46

FCC Part 27


LTE Band 4 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:30:40

1.4MHz_Low_QPSK_6@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:31:11

1.4MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:31:40

1.4MHz_Low_16QAM_6@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:32:10

1.4MHz_High_QPSK_1@5




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:32:45

1.4MHz_High_QPSK_6@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:33:29

1.4MHz_High_16QAM_1@5




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:34:00

1.4MHz_High_16QAM_6@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:34:29

3MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:35:07

3MHz_Low_QPSK_15@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:35:41

3MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:36:14

3MHz_Low_16QAM_15@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:36:48

3MHz_High_QPSK_1@14




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:37:22

3MHz_High_QPSK_15@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:37:56

3MHz_High_16QAM_1@14




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:38:31

3MHz_High_16QAM_15@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:39:05

5MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:39:43

5MHz_Low_QPSK_25@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:40:15

5MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:40:49

5MHz_Low_16QAM_25@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:41:22

5MHz_High_QPSK_1@24




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:41:56

5MHz_High_QPSK_25@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:42:29

5MHz_High_16QAM_1@24




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:43:03

5MHz_High_16QAM_25@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:43:36

10MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:44:25

10MHz_Low_QPSK_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:45:09

10MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:45:52

10MHz_Low_16QAM_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:46:35

10MHz_High_QPSK_1@49




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:47:31

10MHz_High_QPSK_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 18:48:14

10MHz_High_16QAM_1@49




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:48:58

10MHz_High_16QAM_50@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:49:41

15MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:50:37

15MHz_Low_QPSK_75@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:51:28

15MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:52:20

15MHz_Low_16QAM_75@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:53:12

15MHz_High_QPSK_1@74




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:54:05

15MHz_High_QPSK_75@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:54:58

15MHz_High_16QAM_1@74




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:55:52

15MHz_High_16QAM_75@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:56:46

20MHz_Low_QPSK_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:57:57

20MHz_Low_QPSK_100@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
Date: 7.APR.2025 18:59:02

20MHz_Low_16QAM_1@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:00:07

20MHz_Low_16QAM_100@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:01:13

20MHz_High_QPSK_1@99




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:02:17

20MHz_High_QPSK_100@0




ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:03:21

20MHz_High_16QAM_1@99



ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:04:25

20MHz_High_16QAM_100@0



ProjectNo.:2502R24398E-RF Tester:Karl Liang
 Date: 7.APR.2025 19:05:30