



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:00:51

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:01:17

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:01:40

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:02:03

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:02:35

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:03:07

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:03:44

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:04:13

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:04:45

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:05:11

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:05:44

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:06:07

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:06:50

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:07:20

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:07:49

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:08:15

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:08:48

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:09:10

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:09:45

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:10:11

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:10:41

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:11:13

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:11:47

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:12:10

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:12:49

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:13:18

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:13:48

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:14:10

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:14:46

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:15:18

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:15:55

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:16:24

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:16:57

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:17:32

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:18:05

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 25.NOV.2021 23:18:37

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:19:15

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:19:37

Band 5 1.4 MHz Middle QPSK RB6#0 1(30MHz-1GHz)




Date: 25.NOV.2021 23:20:04

Band 5	1.4 MHz	Middle	QPSK	RB6#0	2(1GHz-10GHz)
--------	---------	--------	------	-------	---------------




Date: 25.NOV.2021 23:20:26

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:20:56

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:21:21

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:21:56

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:22:19

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:22:48

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:23:07

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:23:34

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:23:56

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:24:38

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:25:03

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:25:33

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:25:55

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:26:28

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:26:53

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:27:26

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:27:52

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.NOV.2021 23:28:26

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 25.NOV.2021 23:28:45

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)



Date: 25.NOV.2021 23:29:19

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)



Date: 25.NOV.2021 23:29:47