

## Declaration Letter of Changing ID

November 21, 2016

UL Japan, Inc.  
4383-326 Asama-cho, Ise-shi,  
Mie 516-0021 Japan

We Seedsware Corporation, are requesting a change of ID grant for original FCC ID: ANSBP3591 and we will be identifying it with FCC ID: 2AJ9J001.


The equipment is electrically identical and the new product version is identical to the certified product. The module manufacturer is the same. The original test results are applicable and representative of this changed device.

Only FCC ID is different. Meanwhile we submit the following documents. The documents on file with Federal Communications Commission from the original certification remain unchanged and continue to be valid except for these documents.

<input type="checkbox"/>	Test Report
<input type="checkbox"/>	External Photo
<input type="checkbox"/>	Internal Photo
<input checked="" type="checkbox"/>	User Manual
<input checked="" type="checkbox"/>	Label drawing/ location
<input type="checkbox"/>	Block Diagram
<input type="checkbox"/>	Specification
<input type="checkbox"/>	Schematic Diagram
<input type="checkbox"/>	Parts List

Thank you for your attention to this matter.

Sincerely,



Masayuki Tomita  
Seedsware Corporation

Seedsware Corporation

3-7-16, Technostage, Izumi-shi, Osaka 594-1144, Japan

TEL: +81-725-51-1110 FAX: +81-725-51-1103 <http://www.seedsware.co.jp>