





5MHz_High_16QAM_1@24

5MHz_High_16QAM_25@0





10MHz_Low_QPSK_1@0

10MHz_Low_QPSK_50@0




10MHz_Low_16QAM_1@0


10MHz_Low_16QAM_50@0




10MHz_High_QPSK_1@49




10MHz_High_QPSK_50@0



10MHz_High_16QAM_1@49




10MHz_High_16QAM_50@0




LTE Band 17, Normal

5MHz_Low_QPSK_1@0





5MHz_Low_QPSK_25@0





5MHz_Low_16QAM_1@0

5MHz_Low_16QAM_25@0





5MHz_High_QPSK_1@24

5MHz_High_QPSK_25@0




5MHz_High_16QAM_1@24

5MHz_High_16QAM_25@0




10MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:54:08

10MHz_Low_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 31.JUL.2025 11:33:52

10MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:56:26

10MHz_Low_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:57:28

10MHz_High_QPSK_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:58:29

10MHz_High_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 1.JUL.2025 12:59:29

10MHz_High_16QAM_1@49




10MHz_High_16QAM_50@0




LTE Band 38, Normal


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0



5MHz_Low_16QAM_25@0




5MHz_High_QPSK_1@24




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 16:58:04

5MHz_High_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:01:00

5MHz_High_16QAM_1@24




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:06:32

5MHz_High_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:09:34

10MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:14:04

10MHz_Low_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:15:38

10MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:16:38

10MHz_Low_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:17:31

10MHz_High_QPSK_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:32:37

10MHz_High_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:22:49

10MHz_High_16QAM_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:34:48

10MHz_High_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:36:44

15MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:37:37

15MHz_Low_QPSK_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:38:27

15MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:39:42

15MHz_Low_16QAM_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:40:28

15MHz_High_QPSK_1@74




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:41:27

15MHz_High_QPSK_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 17:43:35

15MHz_High_16QAM_1@74




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 22:25:34

15MHz_High_16QAM_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 22:30:41

20MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 22:31:27

20MHz_Low_QPSK_100@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 22:32:10

20MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 22:32:54

20MHz_Low_16QAM_100@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 22:33:38


20MHz_High_QPSK_1@99




20MHz_High_QPSK_100@0



20MHz_High_16QAM_1@99




20MHz_High_16QAM_100@0




LTE Band 66, Normal


1.4MHz_Low_QPSK_1@0



1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:38:05

1.4MHz_Low_16QAM_6@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:38:42

1.4MHz_High_QPSK_1@5




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:39:22

1.4MHz_High_QPSK_6@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:40:00

1.4MHz_High_16QAM_1@5




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:40:38

1.4MHz_High_16QAM_6@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:41:17

3MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:42:01

3MHz_Low_QPSK_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:42:41

3MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:43:21

3MHz_Low_16QAM_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 23:57:33

3MHz_High_QPSK_1@14




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:45:13

3MHz_High_QPSK_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:45:52

3MHz_High_16QAM_1@14




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:46:32

3MHz_High_16QAM_15@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:47:12

5MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:48:00

5MHz_Low_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:48:39

5MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:49:18

5MHz_Low_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:49:59

5MHz_High_QPSK_1@24




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:50:38

5MHz_High_QPSK_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:51:17

5MHz_High_16QAM_1@24




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:51:55

5MHz_High_16QAM_25@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:52:34

10MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:53:27

10MHz_Low_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 23:58:19

10MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:55:18

10MHz_Low_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:56:07

10MHz_High_QPSK_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:56:56

10MHz_High_QPSK_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:57:45

10MHz_High_16QAM_1@49




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:58:33

10MHz_High_16QAM_50@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 14:59:22

15MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:00:26

15MHz_Low_QPSK_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:01:24

15MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:02:23

15MHz_Low_16QAM_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:03:22

15MHz_High_QPSK_1@74




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:04:22

15MHz_High_QPSK_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:05:20

15MHz_High_16QAM_1@74




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:06:19

15MHz_High_16QAM_75@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:07:19

20MHz_Low_QPSK_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:08:36

20MHz_Low_QPSK_100@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:09:47

20MHz_Low_16QAM_1@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:10:58

20MHz_Low_16QAM_100@0




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUN.2025 15:12:07


20MHz_High_QPSK_1@99




20MHz_High_QPSK_100@0



20MHz_High_16QAM_1@99




20MHz_High_16QAM_100@0



LTE B41_2, Normal

5MHz_Low_QPSK_1@0



5MHz_Low_QPSK_25@0

